

STREET #

DIRECTION

STREET

ABB

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS

BEGINYEAR NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATIONS

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES

Stone lintel above all storefronts; 4 storefronts on east facades (one corner); front entry to upper levels in second story bay

STOREFRONT ALTERATIONS

completely altered storefronts in configuration and materials; materials include dryvit, aluminum windows, doors; cedar panels on front of windows [Permit #B82-763 (1982)]

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME


COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE



HISTORIC INFO

No permit # (1991)--demo garage

LANDSCAPE

West side of four lane state highway; northwest corner of Kent and S. Main

PHOTO INFORMATION

ROLL1

FRAMES1

ROLL2

FRAMES2

ROLL3

FRAMES3

DIGITAL PHOTO ID

SURVEY INFORMATION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA

STREET #

DIRECTION

STREET

ABB

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION

DETAILS

BEGINYEAR

OTHER YEAR

DATESOURCE

WALL MATERIAL (current)

WALL MATERIAL 2 (current)

WALL MATERIAL (original)

WALL MATERIAL 2 (original)

SIGNIFICANT FEATURES

ALTERATIONS

PLAN

NO OF STORIES

ROOF TYPE

ROOF MATERIAL

FOUNDATION

PORCH

WINDOW MATERIAL

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

**STOREFRONT
FEATURES**

Display window opening on east front facade; recessed entry at east end of north facade

**STOREFRONT
ALTERATIONS**

Secondary entry and display window on north facade now blocked in; aluminum siding at roofline; downsized display windows framed with wood vertical boards in original openings; downsized door opening with vertical boards

HISTORIC INFORMATION

**HISTORIC
NAME**

**COMMON
NAME**

COST

ARCHITECT

ARCHITECT2

BUILDER

**ARCHITECT
SOURCE**

**HISTORIC
INFO**

LANDSCAPE

West side of state highway;
southwest corner of Kent and South
Main; party wall on south side and
parking lot at rear

PHOTO INFORMATION

ROLL1

FRAMES1

ROLL2

FRAMES2

ROLL3

FRAMES3

**DIGITAL
PHOTO ID**

SURVEY INFORMATION

PREPARER

**PREPARER
ORGANIZATION**

SURVEYDATE

SURVEYAREA

City of ROCKFORD

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY CONTINUATION SHEET

STREET # 1001

STREET S MAIN ST

ADDITIONAL PHOTOS AND INFORMATION

Permit information:

#5138 (1933)--demo 2 story brick store; #36765 (1970)--remove wood windows and block w/ masonry; #41312 (1973)--cut opening and install overhead door; Building Dept. notice (1984)--remodeled into barber shop & store without permits; B85-353 (1985)--remove plate glass, framing in with 2'x4' frame

STREET #

DIRECTION

STREET

ABB

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT
FEATURES

STOREFRONT
ALTERATIONS

HISTORIC INFORMATION

HISTORIC
NAME

COMMON
NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT
SOURCE

HISTORIC
INFO

Constructed as part of City of Rockford's Shopstead Program in 1995. 1997 occupants: Novedades Azteca Jewelry (1003), Maculan Chiropractic Clinic (1005) 1997 owner: Rigoberto & Agapita Delagado (1003), P. Robert Maculan (1005)

LANDSCAPE

Located on west side of South Main Street; front facade faces east; uniform setbacks along a commercial street

PHOTO INFORMATION

ROLL1

FRAMES1

ROLL2

FRAMES2

ROLL3

FRAMES3

DIGITAL
PHOTO ID

SURVEY INFORMATION

PREPARER

PREPARER
ORGANIZATION

SURVEYDATE

SURVEYAREA

STREET #

DIRECTION

STREET

ABB

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION

DETAILS

BEGINYEAR

OTHER YEAR

DATESOURCE

WALL MATERIAL (current)

WALL MATERIAL 2 (current)

WALL MATERIAL (original)

WALL MATERIAL 2 (original)

PLAN

NO OF STORIES

ROOF TYPE

ROOF MATERIAL

FOUNDATION

PORCH

WINDOW MATERIAL

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES


2 storefronts with recessed center entries; main entry to upper floors in center bay; black carrara glass at base of storefront; recessed brick panels on brick piers between bays; soldier course brick lintel across both storefronts and main entry

STOREFRONT ALTERATIONS

extensively altered storefronts; north storefront still has recessed entry but window area is filled with wood; south no longer has recessed entry; most Carrara glass gone, 2 small windows on either side of flush door; window area filled with wood

HISTORIC INFORMATION

HISTORIC NAME	Sarna Building
COMMON NAME	
COST	
ARCHITECT	Bradley, Charles W.
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	building permit



HISTORIC INFO

Original building permit #456 (3/11/1920)--"2 theatre & store"; Other permits: #21776 (1960)--close door & wall openings with block; #84158 (1941)--remodel 1st floor for store

LANDSCAPE

West side of four lane state highway; north side party wall; parking lot to south

PHOTO INFORMATION

ROLL1	3
FRAMES1	9
ROLL2	
FRAMES2	
ROLL3	
FRAMES3	
DIGITAL PHOTO ID	e:\main1009s.jpg

SURVEY INFORMATION

PREPARER	LARA RAMSEY
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	3/8/2005
SURVEYAREA	Barber-Colman

STREET #

DIRECTION

STREET

ABB

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY	<input type="text" value="building"/>	CURRENT FUNCTION	<input type="text" value="Commerce/Trade - business"/>
CONDITION	<input type="text" value="fair"/>	HISTORIC FUNCTION	<input type="text" value="Commerce/Trade - business"/>
INTEGRITY	<input type="text" value="major alterations and/or addition(s)"/>	REASON for SIGNIFICANCE	<input type="text"/>
STOREFRONT INTEGRITY	<input type="text" value="major alterations"/>		
SECONDARY STRUCTURE	<input type="text"/>		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	<input type="text" value="Two Part Commercial Block"/>	PLAN	<input type="text" value="rectangular"/>
DETAILS	<input type="text"/>	NO OF STORIES	<input type="text" value="2"/>
BEGINYEAR	<input type="text" value="1926"/>	ROOF TYPE	<input type="text" value="Flat"/>
OTHER YEAR	<input type="text"/>	ROOF MATERIAL	<input type="text" value="Not visible"/>
DATESOURCE	<input type="text" value="South Main Street Survey"/>	FOUNDATION	<input type="text" value="Concrete - poured"/>
WALL MATERIAL (current)	<input type="text" value="Brick (blonde)"/>	PORCH	<input type="text"/>
WALL MATERIAL 2 (current)	<input type="text"/>	WINDOW MATERIAL	<input type="text" value="Wood"/>
WALL MATERIAL (original)	<input type="text" value="Brick (blonde)"/>	WINDOW MATERIAL	<input type="text"/>
WALL MATERIAL 2 (original)	<input type="text"/>	WINDOW TYPE	<input type="text" value="double hung"/>
		WINDOW CONFIG	<input type="text"/>

SIGNIFICANT FEATURES

ALTERATIONS

**STOREFRONT
FEATURES**


1 storefront with entry at south end of front facade and center display window; main entry to upper floors on north end of front facade; arched transom over display windows & doors; stone hoods above doors; stepped stone decoration above center window

**STOREFRONT
ALTERATIONS**

Aluminum replacement windows in original display window opening; replacement door in original openings; opening in display window transom made for air conditioner

HISTORIC INFORMATION

HISTORIC NAME	Jasper St. Angel Building
COMMON NAME	
COST	
ARCHITECT	Bradley, Charles
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	



**HISTORIC
INFO**

Additional Permits--#741 (1920)--recover roof; #898 (1921)--remodel; #2738 (1926)--remodel (Bradley & Bradley, architects)

LANDSCAPE

midblock on east side of busy 4 lane highway; party wall on south side; parking lot north of building

PHOTO INFORMATION

ROLL1	3
FRAMES1	19
ROLL2	
FRAMES2	
ROLL3	
FRAMES3	
DIGITAL PHOTO ID	e:\main1010s.jpg

SURVEY INFORMATION

PREPARER	JENNIFER KENNY
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	3/8/2005
SURVEYAREA	Barber-Colman

STREET #

DIRECTION

STREET

ABB

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT
FEATURES

STOREFRONT
ALTERATIONS

HISTORIC INFORMATION

HISTORIC
NAME

COMMON
NAME

COST

ARCHITECT Johnson, Richard L.

ARCHITECT2

BUILDER

ARCHITECT
SOURCE

HISTORIC
INFO

Built as part of City of Rockford Shopstead Program

LANDSCAPE

midblock one east side of four lane
state highway; party walls on north
and south sides

PHOTO INFORMATION

ROLL1

FRAMES1

ROLL2

FRAMES2

ROLL3

FRAMES3

DIGITAL
PHOTO ID

e:\main1012s.jpg

SURVEY INFORMATION

PREPARER

LARA RAMSEY

PREPARER
ORGANIZATION

GRANACKI HISTORIC
CONSULTANTS

SURVEYDATE

3/8/2005

SURVEYAREA

Barber-Colman

STREET #

DIRECTION

STREET

ABB

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION

DETAILS

BEGINYEAR

OTHER YEAR

DATESOURCE

WALL MATERIAL (current)

WALL MATERIAL 2 (current)

WALL MATERIAL (original)

WALL MATERIAL 2 (original)

PLAN

NO OF STORIES

ROOF TYPE

ROOF MATERIAL

FOUNDATION

PORCH

WINDOW MATERIAL

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT
FEATURES

STOREFRONT
ALTERATIONS

HISTORIC INFORMATION

HISTORIC
NAME

COMMON
NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT
SOURCE

HISTORIC
INFO

LANDSCAPE

midblock on east side of four lane highway; party walls on north and south sides

PHOTO INFORMATION

ROLL1

FRAMES1

ROLL2

FRAMES2

ROLL3

FRAMES3

DIGITAL
PHOTO ID

SURVEY INFORMATION

PREPARER

PREPARER
ORGANIZATION

SURVEYDATE

SURVEYAREA

STREET #

DIRECTION

STREET

ABB

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

SIGNIFICANT FEATURES WINDOW CONFIG

ALTERATIONS

STOREFRONT FEATURES


completely altered storefront with new configuration and materials--storefront was renovated as City of Rockford Shopstead Project (Swanson Construction Co., contractor)

STOREFRONT ALTERATIONS

storefront renovated--one storefront with center entrance; main entry to upper level at south end of facade; wood vertical board on front facade; Aluminum display windows and door

HISTORIC INFORMATION

HISTORIC NAME	Harbison Building
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	



HISTORIC INFO

Additional Permits--#4280 (1929)--remodel storefront; #3697 (1924)--cement block garage; B81-67 (1981)--repairs to meet code (\$45,000); B93-206--move front entry back

LANDSCAPE

midblock on east side of four lane highway; party walls on north and south sides

PHOTO INFORMATION

ROLL1	3
FRAMES1	16
ROLL2	
FRAMES2	
ROLL3	
FRAMES3	
DIGITAL PHOTO ID	e:\main1016s.jpg

SURVEY INFORMATION

PREPARER	LARA RAMSEY
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	3/8/2005
SURVEYAREA	Barber-Colman

STREET #

DIRECTION

STREET

ABB

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**STOREFRONT
FEATURES**

One storefront with original center recessed bay configuration

**STOREFRONT
ALTERATIONS**

New materials on storefront, including tile bulkhead, Aluminum windows, wood panels on transom; new front & rear doors [permit #31107 (1966)]

HISTORIC INFORMATION

**HISTORIC
NAME**

Angelo Zammuto/Liberty
Market Building

**COMMON
NAME**


COST

ARCHITECT

ARCHITECT2

BUILDER

**ARCHITECT
SOURCE**



**HISTORIC
INFO**

Additional Permits -- #2305 (1926)--balcony; #3615 (1928)--
remodel 2 store fronts; #11223 (1946)--enclose 1st floor of rear
porch; #28955 (1965)--repair fire loss (\$400); #40774 (1973)--
interior remodel (\$5,000)

LANDSCAPE

midblock on east side of busy 4 lane
highway; party walls on north and
south sides of building

PHOTO INFORMATION

ROLL1

3

FRAMES1

15

ROLL2

FRAMES2

ROLL3

FRAMES3

**DIGITAL
PHOTO ID**

e:\main1018s.jpg

SURVEY INFORMATION

PREPARER

LARA RAMSEY

**PREPARER
ORGANIZATION**

GRANACKI HISTORIC
CONSULTANTS

SURVEYDATE

3/8/2005

SURVEYAREA

Barber-Colman

STREET #

DIRECTION

STREET

ABB

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT
FEATURES

STOREFRONT
ALTERATIONS

HISTORIC INFORMATION

HISTORIC
NAME

COMMON
NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT
SOURCE

HISTORIC
INFO

LANDSCAPE

Midblock on west side of busy 4 lane highway; parking lot to north; front sidewalks typical of historic commercial district that are up to storefront

PHOTO INFORMATION

ROLL1

FRAMES1

ROLL2

FRAMES2

ROLL3

FRAMES3

DIGITAL
PHOTO ID

SURVEY INFORMATION

PREPARER

PREPARER
ORGANIZATION

SURVEYDATE

SURVEYAREA

STREET #

DIRECTION

STREET

ABB

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION

DETAILS

BEGINYEAR

OTHER YEAR

DATESOURCE

WALL MATERIAL (current)

WALL MATERIAL 2 (current)

WALL MATERIAL (original)

WALL MATERIAL 2 (original)

PLAN

NO OF STORIES

ROOF TYPE

ROOF MATERIAL

FOUNDATION

PORCH

WINDOW MATERIAL

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**STOREFRONT
FEATURES**

2 storefront with recessed entries side by side in center bay; south and north end entries to upper level; iron columns and parts of original iron window trim; prism glass in transoms above display windows

**STOREFRONT
ALTERATIONS**

Store entrance altered, north entrance covered with vertical boards; vertical board at bulkhead; Aluminum display windows; transoms above doors boarded up

HISTORIC INFORMATION

**HISTORIC
NAME**

Hollenbeck-Bennett Building

**COMMON
NAME**


COST

ARCHITECT


ARCHITECT2

BUILDER

**ARCHITECT
SOURCE**



**HISTORIC
INFO**



LANDSCAPE

midblock on east side of busy 4 lane highway; north party wall; vacant lot south of building

PHOTO INFORMATION

ROLL1

3

FRAMES1

10

ROLL2

FRAMES2

ROLL3

FRAMES3

**DIGITAL
PHOTO ID**

e:\main1020s.jpg

SURVEY INFORMATION

PREPARER

LARA RAMSEY

**PREPARER
ORGANIZATION**

GRANACKI HISTORIC
CONSULTANTS

SURVEYDATE

3/8/2005

SURVEYAREA

Barber-Colman

STREET #

DIRECTION

STREET

ABB

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION

DETAILS

BEGINYEAR

OTHER YEAR

DATESOURCE

WALL MATERIAL (current)

WALL MATERIAL 2 (current)

WALL MATERIAL (original)

WALL MATERIAL 2 (original)

PLAN

NO OF STORIES

ROOF TYPE

ROOF MATERIAL

FOUNDATION

PORCH

WINDOW MATERIAL

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**STOREFRONT
FEATURES**

See continuation sheet.

**STOREFRONT
ALTERATIONS**

Storefront remodeling [Permit #5109 (1933)--storefront & partitions]; ceramic tile bulkhead; aluminum doors and transom (1950s alterations); permit #8622 (1941)--remove partitions & stairways in store

HISTORIC INFORMATION

**HISTORIC
NAME**

Miller, J. Building

**COMMON
NAME**


COST

ARCHITECT


ARCHITECT2

BUILDER

**ARCHITECT
SOURCE**



**HISTORIC
INFO**



LANDSCAPE

midblock on west side of busy 4-lane highway; commercial uses with party walls

PHOTO INFORMATION

ROLL1

3

FRAMES1

13

ROLL2

FRAMES2

ROLL3

FRAMES3

**DIGITAL
PHOTO ID**

e:\main1021s.jpg

SURVEY INFORMATION

PREPARER

JENNIFER KENNY

**PREPARER
ORGANIZATION**

GRANACKI HISTORIC
CONSULTANTS

SURVEYDATE

3/8/2005

SURVEYAREA

Barber-Colman

City of ROCKFORD

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY CONTINUATION SHEET

STREET # 1021

STREET S MAIN ST

ADDITIONAL PHOTOS OR INFORMATION

Storefront Features

two storefronts; entry to upper floors at north end; most of the storefront historic configurations and materials are intact; central entry storefronts with single display windows that rise to transom level; cast iron pilasters between storefronts with foliated ornament; original wood front entry door with wood transom; corbeled, capped brick pilaster next to entry door

STREET # 1025-1029
 DIRECTION S
 STREET MAIN
 ABB ST
 PIN 11-27-276-017
 LOCAL SIGNIFICANCE RATING C
 POTENTIAL IND NR? (Y or N) N
 CRITERIA
 Contributing to a NR DISTRICT? C
 Contributing secondary structure? -
 Listed on existing SURVEY? SM; IHSS; RHPC



GENERAL INFORMATION

CATEGORY building CURRENT FUNCTION Commerce/Trade - business
 CONDITION good HISTORIC FUNCTION Commerce/Trade - business
 INTEGRITY minor alterations and addition(s) REASON for SIGNIFICANCE If not for the aluminum window replacements, this handsome, intact, massive commercial block would be rated significant.
 STOREFRONT INTEGRITY minor alterations
 SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION Two Part Commercial Block PLAN square
 DETAILS Commercial Style NO OF STORIES 3
 BEGINYEAR 1910 ROOF TYPE Flat
 OTHER YEAR ROOF MATERIAL Not visible
 DATESOURCE South Main Street Survey FOUNDATION Concrete - poured
 WALL MATERIAL (current) Brick PORCH
 WALL MATERIAL 2 (current) WINDOW MATERIAL Aluminum
 WALL MATERIAL (original) Brick WINDOW MATERIAL
 WALL MATERIAL 2 (original) WINDOW TYPE double hung/fixe
 WINDOW CONFIG 1/1; single pane

SIGNIFICANT FEATURES See continuation sheet

ALTERATIONS Backlit sign; aluminum double hung replacement windows in original openings; windows boarded up on first floor of south facade; doors changed on south facade

STOREFRONT FEATURES

3 storefronts on east facade with one at corner; central storefront with recessed entry and beveled display windows; north storefront with central entry and beveled display windows; metal frieze with rosette tie rods; classical style iron pilasters

STOREFRONT ALTERATIONS

All storefronts have been remodeled with narrow kick plates and plate glass; corner has been completely reconfigured on an angle with central door, windows and canopy above [permit #25197 (1963) "revamp entrance"]; backlit awning over north storefront

HISTORIC INFORMATION

HISTORIC NAME

Culhane Block

COMMON NAME


COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE



HISTORIC INFO

Listed in 1997 as 1029 South Main Street---See continuation sheet for building permits for 1025, 1027, and 1029

LANDSCAPE

Northwest corner of Morgan and S. Main St., west side of 4 lane state highway; commercial block with party walls

PHOTO INFORMATION

ROLL1

3

FRAMES1

12

ROLL2

FRAMES2

ROLL3

FRAMES3

DIGITAL PHOTO ID

e:\main1025s.jpg

SURVEY INFORMATION

PREPARER

JENNIFER KENNY

PREPARER ORGANIZATION

GRANACKI HISTORIC CONSULTANTS

SURVEYDATE

3/8/3005

SURVEYAREA

Barber-Colman

City of ROCKFORD

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY CONTINUATION SHEET

STREET # 1025 -1029

STREET S MAIN ST

ADDITIONAL PHOTOS OR INFORMATION

Storefront Features

3 bay east facade; corbeled brick frieze with stone cornice line above it; continuous stone sills on upper floors; stone inset name/date panels; terra cotta panels at corner with shell motif; decorative brick parapet with stone coping; projecting brick pilasters at 2nd and 3rd floors that are capped with stone fluted trim, volutes, and end with stone geometric panels with brackets

Permit information:

1025 S. Main Street

#2607 (1925)–remodel storefront; #8907 (1941)–remodel store front; #25197 (1963)–“revamp” entrances; PS86-267 (1986)–remove porch;

1027 S. Main Street

#28668 (1965)–general repairs to 2 story porch

1029 S. Main Street

#5060 (1933)–repair fire loss (\$600); #12796 (1948)–new storefront

STREET #

DIRECTION

STREET

ABB

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS

BEGINYEAR NO OF STORIES

OTHER YEAR

ROOF TYPE

DATESOURCE ROOF MATERIAL

FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT FEATURES


Storefront configuration and materials have been completely altered

STOREFRONT ALTERATIONS

Single storefront with angled display windows and recessed center entry [#12229 (1948)--remodel storefront, build elevator enclosure]; stucco cladding on front facade and west bay of south facade; Aluminum display windows

HISTORIC INFORMATION

HISTORIC NAME	Hudler, W. F. Building
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	



HISTORIC INFO

Additional Permits -- #3864 (1928)--rebuild parapet walls; #6714 (1937)--storefront (\$2000); #43301 (1974)--demo rear porch; #47443 (1976)--construct 15'x20' metal enclosure

LANDSCAPE

northeast corner of S. Main and Morgan; vacant lot north of building

PHOTO INFORMATION

ROLL1	3
FRAMES1	11
ROLL2	
FRAMES2	
ROLL3	
FRAMES3	
DIGITAL PHOTO ID	e:\main1030-1032s.jpg

SURVEY INFORMATION

PREPARER	LARA RAMSEY
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	3/8/2005
SURVEYAREA	Barber-Colman

City of ROCKFORD

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY CONTINUATION SHEET

STREET # 1030 - 1032

STREET S. MAIN ST

ADDITIONAL PHOTOS OR INFORMATION

Significant Features

3 bay front facade with topped with stone-capped parapet; cornice line with dentils and corbeling; inset stone name and date panels; drip molding over 3rd story windows
3-part arched window in center of 3rd story; segmented arch window openings on south facade with stone sills and brick lintels; arched doorway at east end of south facade