

STREET #

DIRECTION

STREET

ABB

PIN

LOCAL SIGNIFICANCE RATING


POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY	<input type="text" value="building"/>	CURRENT FUNCTION	<input type="text" value="Transportation - auto repair/gas station"/>
CONDITION	<input type="text" value="fair"/>	HISTORIC FUNCTION	<input type="text" value="Transportation - auto repair/gas station"/>
INTEGRITY	<input type="text" value="major alterations and/or addition(s)"/>	REASON for SIGNIFICANCE	<input type="text"/>
STOREFRONT INTEGRITY	<input type="text"/>		
SECONDARY STRUCTURE	<input type="text" value="gasoline island"/>		

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	<input type="text" value="Gas Station"/>	PLAN	<input type="text" value="rectangular"/>
DETAILS	<input type="text"/>	NO OF STORIES	<input type="text" value="1"/>
BEGINYEAR	<input type="text" value="1950s"/>	ROOF TYPE	<input type="text" value="Mansard"/>
OTHER YEAR	<input type="text"/>	ROOF MATERIAL	<input type="text" value="Asphalt - shingle"/>
DATESOURCE	<input type="text" value="Surveyor"/>	FOUNDATION	<input type="text" value="Concrete - poured"/>
WALL MATERIAL (current)	<input type="text" value="Steel panels"/>	PORCH	<input type="text"/>
WALL MATERIAL 2 (current)	<input type="text" value="Concrete - block"/>	WINDOW MATERIAL	<input type="text" value="plate glass"/>
WALL MATERIAL (original)	<input type="text" value="Steel panels"/>	WINDOW MATERIAL	<input type="text"/>
WALL MATERIAL 2 (original)	<input type="text"/>	WINDOW TYPE	<input type="text" value="fixed"/>
		WINDOW CONFIG	<input type="text"/>

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT  
FEATURES

STOREFRONT  
ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC  
NAME

COMMON  
NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT  
SOURCE

HISTORIC  
INFO

LANDSCAPE

On southwest corner of S. Main Street & Montague; on busy four lane state highway; mixed uses on street; parking pad, drive, and gas island at front; corrugated metal fencing around rear of building

**PHOTO INFORMATION**

ROLL1

FRAMES1

ROLL2

FRAMES2

ROLL3

FRAMES3

DIGITAL  
PHOTO ID

**SURVEY INFORMATION**

PREPARER

PREPARER  
ORGANIZATION

SURVEYDATE

SURVEYAREA

# City of ROCKFORD

## ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY CONTINUATION SHEET

STREET # 1303

STREET S MAIN ST

---

### ADDITIONAL PHOTOS OR INFORMATION

#### *Alterations*

painted steel panels; mansard roof added [permit #B83-709 (1983)--false roof overhang on 3 sides of building]; N. side window at corner enclosed w/ wood vertical board; replacement overhead garage doors (non-historic); metal security grates over main entry doors & windows; 2 entry doors for bathrooms on N. facade

STREET #

DIRECTION

STREET

ABB

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT  
FEATURES

STOREFRONT  
ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC  
NAME

COMMON  
NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT  
SOURCE

HISTORIC  
INFO

Mexican bar previous to liquor store; permit #33435 (1968)--  
general repairs (\$2500); permit #18992b (1956)--demo club  
rooms (brick)

LANDSCAPE

midblock on west side between  
Montague and Knowlton on S. Main;  
asphalt driveway and parking lot to  
north; front sidewalks; mixed uses on  
block

**PHOTO INFORMATION**

ROLL1

FRAMES1

ROLL2

FRAMES2

ROLL3

FRAMES3

DIGITAL  
PHOTO ID

**SURVEY INFORMATION**

PREPARER

PREPARER  
ORGANIZATION

SURVEYDATE

SURVEYAREA

# City of ROCKFORD

## ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY CONTINUATION SHEET

STREET # 1321

STREET S MAIN ST

---

### ADDITIONAL PHOTOS OR INFORMATION

#### *Significant Features*

brick cladding laid in English bond; basket weave brickwork panels below lower & upper level floor windows on front facade; recessed central entry up stairs with shallow pediment and paired wood doors with 3 diamond screen panels; stone window & entry surrounds; brick rowlock sills on north and south facades

STREET #

DIRECTION

STREET

ABB

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY	<input type="text" value="building"/>	CURRENT FUNCTION	<input type="text" value="Domestic - multiple dwelling"/>
CONDITION	<input type="text" value="fair"/>	HISTORIC FUNCTION	<input type="text" value="Domestic - single dwelling"/>
INTEGRITY	<input type="text" value="minor alterations and addition(s)"/>	REASON for SIGNIFICANCE	<input type="text" value="Except for the front porch, this is a well-preserved example of the early Upright and Wing vernacular type."/>
STOREFRONT INTEGRITY	<input type="text"/>		
SECONDARY STRUCTURE	<input type="text"/>		

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	<input type="text" value="Upright and Wing"/>	PLAN	<input type="text" value="L"/>
DETAILS	<input type="text" value="Greek Revival"/>	NO OF STORIES	<input type="text" value="2 &amp; 1"/>
BEGINYEAR	<input type="text" value="c. 1870"/>	ROOF TYPE	<input type="text" value="Multi-gable"/>
OTHER YEAR	<input type="text"/>	ROOF MATERIAL	<input type="text" value="Asphalt - shingle"/>
DATESOURCE	<input type="text" value="Surveyor"/>	FOUNDATION	<input type="text" value="Stone"/>
WALL MATERIAL (current)	<input type="text" value="Wood"/>	PORCH	<input type="text" value="Wrap around"/>
WALL MATERIAL 2 (current)	<input type="text"/>	WINDOW MATERIAL	<input type="text" value="wood"/>
WALL MATERIAL (original)	<input type="text" value="Wood"/>	WINDOW MATERIAL	<input type="text" value="metal"/>
WALL MATERIAL 2 (original)	<input type="text"/>	WINDOW TYPE	<input type="text" value="double hung/fixd"/>
		WINDOW CONFIG	<input type="text" value="2/2; 1/1; 1 light"/>

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT  
FEATURES

STOREFRONT  
ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME	<input type="text"/>
COMMON NAME	<input type="text"/>
COST	<input type="text"/>
ARCHITECT	<input type="text"/>
ARCHITECT2	<input type="text"/>
BUILDER	<input type="text"/>
ARCHITECT SOURCE	<input type="text"/>

HISTORIC  
INFO

#16135B (1953)--18x6 bathroom between residence & garage;  
#9289 (1928)--garage; B91-1023 (1991)--replace porch (just  
deck?)

LANDSCAPE

Northwest corner of S. Main and  
Knowlton; mixed use street; front  
sidewalk; house on slight rise; rear  
driveway; concrete retaining wall and  
steps at front

**PHOTO INFORMATION**

ROLL1	<input type="text" value="2"/>
FRAMES1	<input type="text" value="24"/>
ROLL2	<input type="text"/>
FRAMES2	<input type="text"/>
ROLL3	<input type="text"/>
FRAMES3	<input type="text"/>
DIGITAL PHOTO ID	<input type="text" value="e:\main1323-1325s.jpg"/>

**SURVEY INFORMATION**

PREPARER	<input type="text" value="JENNIFER KENNY"/>
PREPARER ORGANIZATION	<input type="text" value="GRANACKI HISTORIC CONSULTANTS"/>
SURVEYDATE	<input type="text" value="3/8/2005"/>
SURVEYAREA	<input type="text" value="Barber-Colman"/>

# City of ROCKFORD

## ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY CONTINUATION SHEET

STREET # 1323 -1325

STREET S MAIN ST

---

### ADDITIONAL PHOTOS OR INFORMATION

#### *Alterations*

Two rear one story frame additions (one garage, one wing, both non-historic); metal security grates on many windows; replacement porch rail (non-historic); replacement metal windows in original openings on 1<sup>st</sup> floor of south facade; rear 2<sup>nd</sup> floor wood porch deck

STREET #

DIRECTION

STREET

ABB

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT  
FEATURES

STOREFRONT  
ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC  
NAME

COMMON  
NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT  
SOURCE

HISTORIC  
INFO

Additional Permits -- #37995B (1974)--repair fire damage (\$4800)

LANDSCAPE

Southwest corner of Knowlton Street and S. Main Street; residential on this side of block; concrete retaining wall and steps at front; front sidewalk; chain link fence at side property line

**PHOTO INFORMATION**

ROLL1

FRAMES1

ROLL2

FRAMES2

ROLL3

FRAMES3

DIGITAL  
PHOTO ID

e:\main1403s.jpg

**SURVEY INFORMATION**

PREPARER

JENNIFER KENNY

PREPARER  
ORGANIZATION

GRANACKI HISTORIC  
CONSULTANTS

SURVEYDATE

3/8/2005

SURVEYAREA

Barber-Colman

STREET #

DIRECTION

STREET

ABB

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR  NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATION

PORCH

WALL MATERIAL (current)  WINDOW MATERIAL

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW TYPE

WALL MATERIAL 2 (original)

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT  
FEATURES

STOREFRONT  
ALTERATIONS

HISTORIC INFORMATION

HISTORIC  
NAME

COMMON  
NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT  
SOURCE



HISTORIC  
INFO

LANDSCAPE

Midblock on west side of S. Main  
between Knowlton and Lane; house  
built on rise; concrete block retaining  
walls and steps at front; front  
sidewalk; on busy 4 lane state  
highway

PHOTO INFORMATION

ROLL1

FRAMES1

ROLL2

FRAMES2

ROLL3

FRAMES3

DIGITAL  
PHOTO ID

SURVEY INFORMATION

PREPARER

PREPARER  
ORGANIZATION

SURVEYDATE

SURVEYAREA

STREET #

DIRECTION

STREET

ABB

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR  NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATION

DATE SOURCE  PORCH

WALL MATERIAL (current)  WINDOW MATERIAL

WALL MATERIAL 2 (current)

WALL MATERIAL (original)

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT  
FEATURES

STOREFRONT  
ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC  
NAME

COMMON  
NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT  
SOURCE

HISTORIC  
INFO

LANDSCAPE

Surrounded by asphalt parking lot

**PHOTO INFORMATION**

ROLL1

FRAMES1

ROLL2

FRAMES2

ROLL3

FRAMES3

DIGITAL  
PHOTO ID

e:\main1414s.jpg

**SURVEY INFORMATION**

PREPARER

VICKI GRANACKI

PREPARER  
ORGANIZATION

GRANACKI HISTORIC  
CONSULTANTS

SURVEYDATE

3/17/2005

SURVEYAREA

Barber-Colman

STREET #

DIRECTION

STREET

ABB

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION

DETAILS

BEGINYEAR

OTHER YEAR

DATESOURCE

WALL MATERIAL (current)

WALL MATERIAL 2 (current)

WALL MATERIAL (original)

WALL MATERIAL 2 (original)

PLAN

NO OF STORIES

ROOF TYPE

ROOF MATERIAL

FOUNDATION

PORCH

WINDOW MATERIAL

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT  
FEATURES

STOREFRONT  
ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC  
NAME

COMMON  
NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT  
SOURCE

HISTORIC  
INFO

#11329 (1946)--asbestos shingle siding

LANDSCAPE

Midblock on west side of 4 lane state highway; chain link fencing; concrete retaining wall and concrete step at front; house built on rise

**PHOTO INFORMATION**

ROLL1

FRAMES1

ROLL2

FRAMES2

ROLL3

FRAMES3

DIGITAL  
PHOTO ID

e:\main1421s.jpg

**SURVEY INFORMATION**

PREPARER

PREPARER  
ORGANIZATION

SURVEYDATE

SURVEYAREA

STREET #

DIRECTION

STREET

ABB

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR  NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATION

DATE SOURCE  PORCH

WALL MATERIAL (current)  WINDOW MATERIAL

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT  
FEATURES

STOREFRONT  
ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC  
NAME

COMMON  
NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT  
SOURCE

HISTORIC  
INFO

#2562 (1925)--1 story rear addition (8x12)

LANDSCAPE

Midblock on west side of busy 4 lane  
state highway; concrete retaining  
wall and steps; house built on rise;  
front sidewalk

**PHOTO INFORMATION**

ROLL1

FRAMES1

ROLL2

FRAMES2

ROLL3

FRAMES3

DIGITAL  
PHOTO ID

e:\main1425s.jpg

**SURVEY INFORMATION**

PREPARER

JENNIFER KENNY

PREPARER  
ORGANIZATION

GRANACKI HISTORIC  
CONSULTANTS

SURVEYDATE

3/8/2005

SURVEYAREA

Barber-Colman

STREET #

DIRECTION

STREET

ABB

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT  
FEATURES

STOREFRONT  
ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC  
NAME

COMMON  
NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT  
SOURCE

HISTORIC  
INFO

LANDSCAPE

On west side of S. Main Street;  
concrete retaining wall and steps at  
front; house on rise; front wood  
fencing; front sidewalk

**PHOTO INFORMATION**

ROLL1

FRAMES1

ROLL2

FRAMES2

ROLL3

FRAMES3

DIGITAL  
PHOTO ID

e:\main1427s.jpg

**SURVEY INFORMATION**

PREPARER

PREPARER  
ORGANIZATION

SURVEYDATE

SURVEYAREA

# City of ROCKFORD

## ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY CONTINUATION SHEET

STREET # 1427

STREET S MAIN ST

---

### ADDITIONAL PHOTOS OR INFORMATION

#### *Alterations*

Rear shed roof south and north side dormers [permit #12024 (1947)--raise roof to provide for bedroom]; rear one story shed roof addition; aluminum siding [permit #34305 (1969)--aluminum siding]; boarded up 1st floor windows due to fire; downsized 2nd floor windows in original openings; shutters added; replacement front porch (non-historic); exterior staircase added to south side at rear

STREET #

DIRECTION

STREET

ABB

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR  NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

DATE SOURCE  WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT  
FEATURES

STOREFRONT  
ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC  
NAME

COMMON  
NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT  
SOURCE

HISTORIC  
INFO

LANDSCAPE

Midblock on west side of 4 lane state highway; concrete retaining walls and steps at front; house built on rise; front sidewalks with telephone poles

**PHOTO INFORMATION**

ROLL1

FRAMES1

ROLL2

FRAMES2

ROLL3

FRAMES3

DIGITAL  
PHOTO ID

e:\main1429s.jpg

**SURVEY INFORMATION**

PREPARER

PREPARER  
ORGANIZATION

SURVEYDATE

SURVEYAREA

STREET #

DIRECTION

STREET

ABB

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR  NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATION

PORCH

WALL MATERIAL (current)  WINDOW MATERIAL

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT  
FEATURES

STOREFRONT  
ALTERATIONS

HISTORIC INFORMATION

HISTORIC  
NAME

COMMON  
NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT  
SOURCE

HISTORIC  
INFO

#3413 (1927)--remodel for 2 family

LANDSCAPE

Midblock on west side of busy 4 lane  
state highway; concrete retaining  
walls and steps at front; house on  
rise; front sidewalk; telephone poles  
at front

PHOTO INFORMATION

ROLL1

FRAMES1

ROLL2

FRAMES2

ROLL3

FRAMES3

DIGITAL  
PHOTO ID

e:\main1435s.jpg

SURVEY INFORMATION

PREPARER

PREPARER  
ORGANIZATION

SURVEYDATE

SURVEYAREA

STREET #

DIRECTION

STREET

ABB

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR  NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT  
FEATURES

STOREFRONT  
ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC  
NAME

COMMON  
NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT  
SOURCE



HISTORIC  
INFO

Additional Permit -- #7875 (1940)--8x12 chimney flue lined

LANDSCAPE

Midblock on west side of busy 4 lane  
state highway; residential block;  
poured concrete retaining wall and  
steps at front; shallow front  
sidewalks; parking pad at rear

**PHOTO INFORMATION**

ROLL1

11

FRAMES1

21-22

ROLL2

FRAMES2

ROLL3

FRAMES3

DIGITAL  
PHOTO ID

e:\main1437s.jpg

**SURVEY INFORMATION**

PREPARER

JENNIFER KENNY

PREPARER  
ORGANIZATION

GRANACKI HISTORIC  
CONSULTANTS

SURVEYDATE

3/8/2005

SURVEYAREA

Barber-Colman

# City of ROCKFORD

## ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY CONTINUATION SHEET

STREET # 1437

STREET S MAIN ST

---

### ADDITIONAL PHOTOS OR INFORMATION

#### *Significant Features*

Full height north side bay; decorative window hoods; decorative circular window on N. façade with pedimented hood and panel below; 1st floor bay window with decorative wood brackets and panels above windows; flat canopy over secondary front entry with wood brackets; ornamental wood door surrounds

STREET #

DIRECTION

STREET

ABB

PIN

LOCAL SIGNIFICANCE RATING


POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**STOREFRONT  
FEATURES**

3 bay single storefront

**STOREFRONT  
ALTERATIONS**

Storefront has been completely altered (includes configuration and materials); brick ?? And single entry door with transom-  
height Aluminum windows [Permit #43658 (1974)-remove glass and brick up, repair stucco as necessary]

**HISTORIC INFORMATION**

**HISTORIC  
NAME**

**COMMON  
NAME**


**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT  
SOURCE**



**HISTORIC  
INFO**

See continuation sheet for additional building permits.

**LANDSCAPE**

North west corner of Salter Avenue  
and S. Main Street; lot slopes  
upward toward rear; front and side  
sidewalks

**PHOTO INFORMATION**

**ROLL1**

**FRAMES1**

**ROLL2**

**FRAMES2**

**ROLL3**

**FRAMES3**

**DIGITAL  
PHOTO ID**

**SURVEY INFORMATION**

**PREPARER**

**PREPARER  
ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**

# City of ROCKFORD

## ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY CONTINUATION SHEET

STREET # 1441

STREET S. MAIN ST

---

### ADDITIONAL PHOTOS AND INFORMATION

*Permit information:*

#5637B (1935)--remodel storefront; #5587 (1955)--2nd story porch addition, 6x18 open stairway leading to ground 1 family; #27160 (1964)--repair damage to storefront; #35181 (1969)--repair side entrance steps

This is to CERTIFY that the images appearing on this file are TRUE, ACCURATE and COMPLETE REPRODUCTIONS of the records of THE CITY OF MOOREHEAD, MISSISSIPPI, and are created in the normal course of business.

*Robert Colman* 8-3-74

1441 S. Main St.

Per No. 43658 B

Location 1441 So. Main Street

Owner Holliness Church of God

Contractor Robert Colman

Architect \_\_\_\_\_

Class of Work Remove glass and brick up. - repair stucco as necessary - \$1,000.

Legal \_\_\_\_\_

Date Issued July 30 19 74

ruff RT final R. to O. 11-8-74

(11-8-74)

Per No. 35181B

Location 1441 So. Main St.

Owner Holliness Church of God

Contractor Henry Coleman

Architect \_\_\_\_\_

Class of Work repair side entrance steps \$300.

Legal \_\_\_\_\_

Date Issued July 28 1969

Per No. 27160 B

Location 1441 S. Main Street

Owner \_\_\_\_\_

Contractor Theo Malez

Architect \_\_\_\_\_

Class of Work Repair store front damaged by car. also use rod and plate & close works in brick

Legal wall \$400

Date Issued June 29 19 64

Per No. 5587B

Street & No. 1441 S Main St

Owner Frank Fuca

Contractor \_\_\_\_\_

Architect \_\_\_\_\_

Class of Work 2nd st porch add 5x18 open stairway leading to ground 1 fee

Remarks \$ 150

Date Issued Aug 5 193 5