

STREET #

DIRECTION

STREET

ABB

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT
FEATURES

STOREFRONT
ALTERATIONS

HISTORIC INFORMATION

HISTORIC
NAME

COMMON
NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT
SOURCE



HISTORIC
INFO

LANDSCAPE

Unmarked baseball diamond with chain link backstop; goalposts; 2 basketball hoops on concrete pad; 2 tennis courts; playground; bordered on east side by river.

PHOTO INFORMATION

ROLL1

FRAMES1

ROLL2

FRAMES2

ROLL3

FRAMES3

DIGITAL
PHOTO ID

SURVEY INFORMATION

PREPARER

PREPARER
ORGANIZATION

SURVEYDATE

SURVEYAREA

STREET #

DIRECTION

STREET

ABB

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS

BEGINYEAR NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATION

PORCH

WALL MATERIAL (current) WINDOW MATERIAL

WALL MATERIAL 2 (current)

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT
FEATURES

STOREFRONT
ALTERATIONS

HISTORIC INFORMATION

HISTORIC
NAME

COMMON
NAME


COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT
SOURCE



HISTORIC
INFO

Cement block garage [Permit #3766 (1924)] replaced in 1974 with a 2 car garage [permit #42170 (1974)--2 car garage]

LANDSCAPE

Southwest corner of Rock (100 W) and Lane (400 S); house built on slight rise; chain link fence on west property line; front sidewalk

PHOTO INFORMATION

ROLL1

FRAMES1

ROLL2

FRAMES2

ROLL3

FRAMES3

DIGITAL
PHOTO ID

SURVEY INFORMATION

PREPARER

PREPARER
ORGANIZATION

SURVEYDATE

SURVEYAREA

City of ROCKFORD

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY CONTINUATION SHEET

STREET # 206

STREET LANE ST

ADDITIONAL PHOTOS OR INFORMATION

Alterations

Aluminum siding; replacement aluminum windows in original openings; enclosed full width front porch (non-historic); Aluminum eaves; 2 story frame historic rear addition (c. 1900) with through-the-cornice dormers; rear porch addition (non-historic); enlarged front windows at 2nd floor on front facade; replacement doors; 7'-6"x22' open rear porch [Permit #14152 (1950)]; repairs to porch [Permit #28672 (1965)]

STREET #

DIRECTION

STREET

ABB

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS

BEGINYEAR NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT
FEATURES

STOREFRONT
ALTERATIONS

HISTORIC INFORMATION

HISTORIC
NAME

COMMON
NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT
SOURCE

HISTORIC
INFO

Permit #4829 (1939)--demo shed; Permit #16084 (1953)--cut door in 2nd floor and construct exterior stair

LANDSCAPE

Midblock on mostly vacant residential street; side driveway; house on slight rise; front sidewalk

PHOTO INFORMATION

ROLL1

FRAMES1

ROLL2

FRAMES2

ROLL3

FRAMES3

DIGITAL
PHOTO ID

SURVEY INFORMATION

PREPARER

PREPARER
ORGANIZATION

SURVEYDATE

SURVEYAREA