



ROCKFORD FIRE DEPARTMENT INCIDENT UPDATE

Incident Information

Business Name: Residential Garage Fire

Address of Incident: 932 South Gregory

Date of Incident: 7/2/2016

Time of Incident: 01:07

Type of Incident: Residential Structure Fire

Cause of Fire: Undetermined

Estimated Loss: \$10,000

Injury Data

Civilian Injuries: 0

Civilian Deaths: 0

Fire Department Response

Engine(s): 3

Ladder(s): 0

District Chief(s): 2

Quint(s): 2

Ambulance(s): 1

Haz Mat Unit(s): 0

Boat(s): 0

Diver(s): 0

Other(s): 0

Total Firefighters: 21

Response Time: 3 min

Narrative

The Rockford Fire Department responded to an unattached garage fire at a vacant residence. The first arriving unit report a fully involved structure. The first engine crew deployed a fast attack hose line and began extinguishing the fire. The next arriving engine crew established a positive water supply and deployed a second hose line. The fire was difficult to extinguish because the garage was filled with roofing material. The fire crews ultimately used foam to help smother the fire. The neighboring residence sustained siding damage due to the intense heat. The cause is unknown and still under investigation.

For additional information contact: 779-348-7172

Prepared by: Capt. John Dempsey on 7/2/2016 at 21:19