

STREET #

DIRECTION

STREET

ABB

PIN

LOCAL SIGNIFICANCE RATING


POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT  
FEATURES

STOREFRONT  
ALTERATIONS

**HISTORIC INFORMATION**

|                  |                                 |
|------------------|---------------------------------|
| HISTORIC NAME    | Rockford Union Foundry          |
| COMMON NAME      | Sundstrand Machine Tool Foundry |
| COST             |                                 |
| ARCHITECT        |                                 |
| ARCHITECT2       |                                 |
| BUILDER          |                                 |
| ARCHITECT SOURCE |                                 |

HISTORIC  
INFO

Building was once part of the Rockford Union Foundry, later the Sundstrand Machine and Tool Foundry. 221 Loomis was once part of the complex. See continuation sheet for building permits.

LANDSCAPE

North side of street in industrial area; RR tracks curve to east and north; across street from Barber-Coleman property; at Northwest corner of River and Loomis River is a dead end street.

**PHOTO INFORMATION**

|                  |                  |
|------------------|------------------|
| ROLL1            | 4                |
| FRAMES1          | 14               |
| ROLL2            |                  |
| FRAMES2          |                  |
| ROLL3            |                  |
| FRAMES3          |                  |
| DIGITAL PHOTO ID | e:\river1129.jpg |

**SURVEY INFORMATION**

|                       |                               |
|-----------------------|-------------------------------|
| PREPARER              | JENNIFER KENNY                |
| PREPARER ORGANIZATION | GRANACKI HISTORIC CONSULTANTS |
| SURVEYDATE            | 3/17/2005                     |
| SURVEYAREA            | Barber-Colman                 |

# City of ROCKFORD

## ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY CONTINUATION SHEET

STREET # 1129

STREET RIVER ST

---

### ADDITIONAL PHOTOS AND INFORMATION

*Permit information:*

#3711 (1926)—repair fire damage; #5227 (1934)—new roof; #6248 (1936)—new steel sash; #6425 (1937)—replace brick column w/ steel, adding balcony in storage building; #7640 (1939)—columns for crane and repair roof; #10445 (1944)—install mono-rail; #11738 (1947)—frame vestibule in foundry; #16339 (1953)—remodel office

Permits that were listed under 1129 River and are likely for 221 Loomis (building once part of complex:

#513 (1920)—addition; #2915 (1925)—1 story addition to frame coal shed in angle of building; #3183 (1927)—1 story addition to core room and 1 story addition to blast room; #5659 (1935)—1 story brick & steel addition (39x45) for storage

This is to CERTIFY that the images appearing on this film are ACTUAL, ACCURATE AND COMPLETE REPRODUCTIONS of the records of THE CITY OF ROCKFORD BUILDING DEPARTMENT and are created in the normal course of business.

Sherrill J. J. J. 9.14.92  
CAMERA OPERATOR DATE

1129 River St.

|               |                                       |         |        |
|---------------|---------------------------------------|---------|--------|
| Street & No.  | 1129 River St                         | Per No. | 10445B |
| Owner         | Sundstrand Mah Tool Co                |         |        |
| Contractor    | Linden & Sons, Inc                    |         |        |
| Architect     |                                       |         |        |
| Class of Work | install mono-rail and general repairs |         |        |
|               | \$ 900                                |         |        |
| Lot           | Blk.                                  | Add.    |        |
| Date Issued   | Dec 5                                 |         | 1944   |

|               |                                 |         |         |
|---------------|---------------------------------|---------|---------|
| Street & No.  | 1129 River St.                  | Per No. | 11738-B |
| Owner         | Sundstrand Foundry              |         |         |
| Contractor    | Linden & Sons, Inc.             |         |         |
| Architect     |                                 |         |         |
| Class of Work | 5x10 frame vestibule on foundry |         | \$360   |
| Lot           | Blk.                            | Add.    |         |
| Date Issued   |                                 | May 5th | 1947    |

|               |   |           |         |
|---------------|---|-----------|---------|
| Street & No.  | 1129 River St                             | Per No.   | 14595-B |
| Owner         | Sundstrand Machine & Tool Co Foundry Div. |           |         |
| Contractor    | Linden & Sons                             |           |         |
| Architect     |   |           |         |
| Class of Work | Remodel locker and toilet rooms           |           |         |
|               | \$2000                                    |           |         |
| Lot           | Blk.                                      | Add.      |         |
| Date Issued   |   | July 24th | 1951    |

|               |                    |         |        |
|---------------|--------------------|---------|--------|
| Location      | 1129 River St.     | Per No. | 16339B |
| Owner         | Sundstrand Foundry |         |        |
| Contractor    | Linden & Sons Inc  |         |        |
| Architect     |                    |         |        |
| Class of Work | Remodel office     |         | \$2500 |
| Lot           | Blk.               | Add.    |        |
| Date Issued   |                    | Dec. 8, | 1951   |