

STREET #

DIRECTION

STREET

ABB

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT
FEATURES

STOREFRONT
ALTERATIONS

HISTORIC INFORMATION

HISTORIC
NAME

Rockford Steel and Bolt
Company

COMMON
NAME

Rockford Steel and Bolt
Company

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT
SOURCE

HISTORIC
INFO

According to a 1950s Sanborn Insurance Map, Rockford Steel and Bolt Company had its Steel Storage, Raw Steel Storage, Storage of Iron Bars and Forge Shop in this building.

LANDSCAPE

At the corner of Kent and Rock, just north of the railroad tracks, Kent Creek runs behind (northerly) buildings

PHOTO INFORMATION

ROLL1

4

FRAMES1

24-26

ROLL2

FRAMES2

ROLL3

FRAMES3

DIGITAL
PHOTO ID

e:\rock1000.jpg

SURVEY INFORMATION

PREPARER

VICKI GRANACKI

PREPARER
ORGANIZATION

GRANACKI HISTORIC
CONSULTANTS

SURVEYDATE

3/17/2005

SURVEYAREA

Barber-Colman



City of ROCKFORD

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY CONTINUATION SHEET

STREET # 1000

STREET ROCK ST

ADDITIONAL PHOTOS OR INFORMATION



STREET #

DIRECTION

STREET

ABB

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

Concrete block in window openings; brick infill; changed garage door openings; interior partitions [permit #21202 (1959)]; see continuation sheet for more permits

STOREFRONT
FEATURES

STOREFRONT
ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME	Olde Time Cab Company
COMMON NAME	Rokt
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC
INFO

LANDSCAPE

At north end of Rock Street; east (front) façade with no setback; no sidewalk, curb

PHOTO INFORMATION

ROLL1	3
FRAMES1	6-8
ROLL2	
FRAMES2	
ROLL3	
FRAMES3	
DIGITAL PHOTO ID	e:\rock1025.jpg

SURVEY INFORMATION

PREPARER	VICKI GRANACKI
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	3/17/2005
SURVEYAREA	Barber-Colman

City of ROCKFORD

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY CONTINUATION SHEET

STREET # 1025

STREET ROCK ST

ADDITIONAL PHOTOS OR INFORMATION



City of ROCKFORD

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY CONTINUATION SHEET

STREET # 1025

STREET ROCK ST

ADDITIONAL PHOTOS OR INFORMATION

Permits listed for 203 Morgan but are now 1025 Rock: (1940)–1 story rear addition (10x19); #10927 (1945)–one story cement block addition (40x70) to enlarge garage storage; #11032 (1946)–one story cement block addition to warehouse (36x75)

STREET #

DIRECTION

STREET

ABB

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS

BEGINYEAR NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT
FEATURES

STOREFRONT
ALTERATIONS

HISTORIC INFORMATION

HISTORIC
NAME

COMMON
NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT
SOURCE

HISTORIC
INFO

LANDSCAPE

Midblock on west side of street;
asphalt parking lot and chain link
fence at front

PHOTO INFORMATION

ROLL1

FRAMES1

ROLL2

FRAMES2

ROLL3

FRAMES3

DIGITAL
PHOTO ID

SURVEY INFORMATION

PREPARER

PREPARER
ORGANIZATION

SURVEYDATE

SURVEYAREA

City of ROCKFORD

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY CONTINUATION SHEET

STREET # 1109

STREET ROCK ST

ADDITIONAL PHOTOS OR INFORMATION

Alterations

All openings have been enclosed with block or bricked in, except for a garage door on front façade (replacement overhead door) and current entry (replacement door); full width metal canopy and platform added across front façade with concrete block [#11182 (1946)--concrete loading platform and #7805 (1940)--24x35 platform]; #19854 (1958)--remodeling (\$3000); B81-762 (1981)--1 story south side addition (66x31)

STREET #

DIRECTION

STREET

ABB

PIN

LOCAL SIGNIFICANCE RATING


POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS

BEGINYEAR NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATION

DATE SOURCE PORCH

WALL MATERIAL (current) WINDOW MATERIAL

WALL MATERIAL 2 (current)

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT
FEATURES

STOREFRONT
ALTERATIONS

HISTORIC INFORMATION

HISTORIC
NAME

COMMON
NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT
SOURCE

HISTORIC
INFO

Additional permits -- #374 (1920)--reshingle house; #4510 (1930)--addition to warehouse(?); #9845 (1943)--enclose space between buildings for a garage; #10248 (1944)--insul-brick siding

LANDSCAPE

Midblock on east side of street; front sidewalk; grassy lawn and parking

PHOTO INFORMATION

ROLL1

FRAMES1

ROLL2

FRAMES2

ROLL3

FRAMES3

DIGITAL
PHOTO ID

SURVEY INFORMATION

PREPARER

PREPARER
ORGANIZATION

SURVEYDATE

SURVEYAREA

City of ROCKFORD

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY
CONTINUATION SHEET

STREET # 1110

STREET ROCK ST

ADDITIONAL PHOTOS OR INFORMATION



STREET #

DIRECTION

STREET

ABB

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS

BEGINYEAR NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATION

PORCH

WALL MATERIAL (current) WINDOW MATERIAL

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW TYPE

WALL MATERIAL 2 (original) WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**STOREFRONT
FEATURES**

One storefront with side entry and one display window; entry to 2nd floor at side

**STOREFRONT
ALTERATIONS**

Boarded display window & boarded transoms above doors replacement doors in original openings

HISTORIC INFORMATION

**HISTORIC
NAME**

**COMMON
NAME**


COST

ARCHITECT

ARCHITECT2

BUILDER

**ARCHITECT
SOURCE**



**HISTORIC
INFO**

LANDSCAPE

Midblock on east side of street;
parking in parkway; no setback;
mixed uses on street

PHOTO INFORMATION

ROLL1

FRAMES1

ROLL2

FRAMES2

ROLL3

FRAMES3

**DIGITAL
PHOTO ID**

SURVEY INFORMATION

PREPARER

**PREPARER
ORGANIZATION**

SURVEYDATE

SURVEYAREA

STREET #

DIRECTION

STREET

ABB

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS

BEGINYEAR NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**STOREFRONT
FEATURES**

**STOREFRONT
ALTERATIONS**

changing 1st floor from store to 1 family apartment; rock lath, plaster partitions [Permit #77408 (1940)]; downsized windows on either side of front door

HISTORIC INFORMATION

**HISTORIC
NAME**

**COMMON
NAME**


COST

ARCHITECT

ARCHITECT2

BUILDER

**ARCHITECT
SOURCE**



**HISTORIC
INFO**

LANDSCAPE

Midblock on east side of street;
concrete sidewalk and parking; small
grass front and side lawn

PHOTO INFORMATION

ROLL1

4

FRAMES1

29,34

ROLL2

FRAMES2

ROLL3

FRAMES3

**DIGITAL
PHOTO ID**

e:\rock1122.jpg

SURVEY INFORMATION

PREPARER

VICKI GRANACKI

**PREPARER
ORGANIZATION**

GRANACKI HISTORIC
CONSULTANTS


SURVEYDATE

3/17/2005

SURVEYAREA

Barber-Colman

STREET # 1123-1127
 DIRECTION
 STREET ROCK
 ABB ST
 PIN 11-27-280-016
 LOCAL SIGNIFICANCE RATING NC
 POTENTIAL IND NR? (Y or N) N
 CRITERIA
 Contributing to a NR DISTRICT? NC
 Contributing secondary structure? -
 Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY building CURRENT FUNCTION Transportation - road-related (vehicular)
 CONDITION good HISTORIC FUNCTION Transportation - road-related (vehicular)
 INTEGRITY minor alterations and addition(s) REASON for SIGNIFICANCE
 STOREFRONT INTEGRITY
 SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION Garage PLAN rectangular
 DETAILS NO OF STORIES 1
 BEGINYEAR 1965 ROOF TYPE Flat
 OTHER YEAR ROOF MATERIAL Not visible
 DATESOURCE Building Permit FOUNDATION Concrete - poured
 WALL MATERIAL (current) Concrete - block PORCH
 WALL MATERIAL 2 (current) Brick WINDOW MATERIAL Metal
 WALL MATERIAL (original) Concrete - block WINDOW MATERIAL
 WALL MATERIAL 2 (original) WINDOW TYPE Fixed/awning
 WINDOW CONFIG 6-light

SIGNIFICANT FEATURES Two garage bays on short (street) end; pedestrian door on long (4 bay) façade

ALTERATIONS Replacement overhead garage doors in bay; 2 story yellow brick southwest corner addition (approx. 86x78) to existing repair garage that has one full height garage bay [Permit #38618 (1971)]; metal antennae

STOREFRONT
FEATURES

STOREFRONT
ALTERATIONS

HISTORIC INFORMATION

HISTORIC
NAME

COMMON
NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT
SOURCE



HISTORIC
INFO

Original permit #34428 (1965)--33x61 ordinary construction repair garage

LANDSCAPE

Northwest corner of Loomis and Rock; concrete drive and parking at front

PHOTO INFORMATION

ROLL1

FRAMES1

ROLL2

FRAMES2

ROLL3

FRAMES3

DIGITAL
PHOTO ID

SURVEY INFORMATION

PREPARER

JENNIFER KENNY

PREPARER
ORGANIZATION

GRANACKI HISTORIC
CONSULTANTS

SURVEYDATE

3/17/2005

SURVEYAREA

Barber-Colman

STREET #

DIRECTION

STREET

ABB

PIN

LOCAL SIGNIFICANCE RATING


POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS

BEGINYEAR NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATIONSOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT
FEATURES

STOREFRONT
ALTERATIONS

HISTORIC INFORMATION

HISTORIC
NAME

COMMON
NAME


COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT
SOURCE



HISTORIC
INFO

LANDSCAPE

Midblock on east side of street;
sidewalk and grass; parking; fence;
side drive to rear warehouse
structure

PHOTO INFORMATION

ROLL1

FRAMES1

ROLL2

FRAMES2

ROLL3

FRAMES3

DIGITAL
PHOTO ID

SURVEY INFORMATION

PREPARER

PREPARER
ORGANIZATION

SURVEYDATE

SURVEYAREA

STREET # 1519
 DIRECTION
 STREET ROCK
 ABB ST
 PIN 11-27-429-010
 LOCAL SIGNIFICANCE RATING NC
 POTENTIAL IND NR? (Y or N) N
 CRITERIA
 Contributing to a NR DISTRICT? NC
 Contributing secondary structure? -
 Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY building CURRENT FUNCTION Domestic - single dwelling
 CONDITION good HISTORIC FUNCTION Domestic - single dwelling
 INTEGRITY major alterations and/or addition(s) REASON for SIGNIFICANCE
 STOREFRONT INTEGRITY
 SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION No style PLAN rectangular
 DETAILS NO OF STORIES 1
 BEGINYEAR ROOF TYPE Cross gable
 OTHER YEAR 2004 ROOF MATERIAL Asphalt - shingle
 DATESOURCE Surveyor FOUNDATION Limestone/parged
 WALL MATERIAL (current) Vinyl PORCH
 WALL MATERIAL 2 (current) WINDOW MATERIAL Aluminum
 WALL MATERIAL (original) Wood WINDOW MATERIAL
 WALL MATERIAL 2 (original) WINDOW TYPE double hung
 WINDOW CONFIG 1/1

SIGNIFICANT FEATURES Original part of house may have been an upright and wing; now only wing portion has survived

ALTERATIONS Fire in June 2004; currently being renovated; vinyl siding; aluminum windows; rebuilt front gable portion with concrete block foundation [permit # B82-226 (1982)-12x14 front room addition]

STOREFRONT
FEATURES

STOREFRONT
ALTERATIONS

HISTORIC INFORMATION

HISTORIC
NAME

COMMON
NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT
SOURCE

HISTORIC
INFO

Additional permits -- #3888 (1928)--rear addition; #29944
(1966)--Aluminum siding

LANDSCAPE

Only house on block of residential
street; many vacant lots; house on
slight rise; side driveway to south;
front sidewalk

PHOTO INFORMATION

ROLL1

FRAMES1

ROLL2

FRAMES2

ROLL3

FRAMES3

DIGITAL
PHOTO ID

SURVEY INFORMATION

PREPARER

PREPARER
ORGANIZATION

SURVEYDATE

SURVEYAREA