

STREET #

DIRECTION

STREET

ABB

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS

BEGINYEAR NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATIONS

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT
FEATURES

STOREFRONT
ALTERATIONS

HISTORIC INFORMATION

HISTORIC
NAME

COMMON
NAME

Barron Industries


COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT
SOURCE



HISTORIC
INFO

LANDSCAPE

Next to River and elevated Morgan
Street; large parking lot to west

PHOTO INFORMATION

ROLL1

FRAMES1

ROLL2

FRAMES2

ROLL3

FRAMES3

DIGITAL
PHOTO ID

SURVEY INFORMATION

PREPARER

VICKI GRANACKI

PREPARER
ORGANIZATION

GRANACKI HISTORIC
CONSULTANTS

SURVEYDATE

3/17/2005

SURVEYAREA

Barber-Colman

STREET #

DIRECTION

STREET

ABB

PIN

LOCAL SIGNIFICANCE RATING


POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT
FEATURES

STOREFRONT
ALTERATIONS

HISTORIC INFORMATION

HISTORIC
NAME

COMMON
NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT
SOURCE



HISTORIC
INFO

See continuation sheet for additional building permits.

LANDSCAPE

Midblock on north side at end of Bridge; driveway into property at the west; lot slopes to east; industrial uses; concrete parking lot at rear

PHOTO INFORMATION

ROLL1

FRAMES1

ROLL2

FRAMES2

ROLL3

FRAMES3

DIGITAL
PHOTO ID

SURVEY INFORMATION

PREPARER

PREPARER
ORGANIZATION

SURVEYDATE

SURVEYAREA

City of ROCKFORD

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY CONTINUATION SHEET

STREET # 149

STREET MORGAN ST

ADDITIONAL PHOTOS OR INFORMATION

Alterations

2 historic additions to east [permit #2115 (1924)–1 story addition; permit #19699 (1957)–1 story east side masonry addition (20x36)]; one 1 story brick addition with garage bay [#1277 (1922)–20x18 open shed addition to west side of present frame building]; one concrete block addition with truck platform and garage bay and ceramic tile copings [#9246 (1942)–one story + basement cement block and brick addition (16x23)]

ADDITIONAL PERMIT INFORMATION

#2215 (1924)–remodeling frame building & 8" brick fire wall; #16895 (1954)–retaining wall; #19404 (1957)–block wall to support roof; #33328 (1964)–parking shelter (frame); #30344 (1966)–repairing windows, tuck pointing, panel walls

STREET #

DIRECTION

STREET

ABB

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

| | | | |
|----------------------|--|-------------------------|--|
| CATEGORY | <input type="text" value="building"/> | CURRENT FUNCTION | <input type="text" value="Commerce/Trade - business"/> |
| CONDITION | <input type="text" value="fair"/> | HISTORIC FUNCTION | <input type="text" value="Unknown"/> |
| INTEGRITY | <input type="text" value="minor alterations"/> | REASON for SIGNIFICANCE | <input type="text"/> |
| STOREFRONT INTEGRITY | <input type="text"/> | | |
| SECONDARY STRUCTURE | <input type="text" value="detached garage"/> <input type="text" value="detached garage"/> | | |

ARCHITECTURAL DESCRIPTION

| | | | |
|------------------------------|---|-----------------|--|
| ARCHITECTURAL CLASSIFICATION | <input type="text" value="Industrial"/> | PLAN | <input type="text" value="square"/> |
| DETAILS | <input type="text"/> | NO OF STORIES | <input type="text" value="1"/> |
| BEGINYEAR | <input type="text" value="c. 1915"/> | ROOF TYPE | <input type="text" value="Flat"/> |
| OTHER YEAR | <input type="text" value="1939"/> | ROOF MATERIAL | <input type="text" value="Not visible"/> |
| DATESOURCE | <input type="text" value="surveyor"/> | FOUNDATION | <input type="text" value="Concrete - poured"/> |
| WALL MATERIAL (current) | <input type="text" value="Brick"/> | PORCH | <input type="text" value="Side car port"/> |
| WALL MATERIAL 2 (current) | <input type="text"/> | WINDOW MATERIAL | <input type="text" value="Vinyl"/> |
| WALL MATERIAL (original) | <input type="text" value="Brick"/> | WINDOW MATERIAL | <input type="text"/> |
| WALL MATERIAL 2 (original) | <input type="text"/> | WINDOW TYPE | <input type="text" value="double hung"/> |
| | | WINDOW CONFIG | <input type="text" value="1/1"/> |

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT
FEATURES

STOREFRONT
ALTERATIONS

HISTORIC INFORMATION

HISTORIC
NAME

COMMON
NAME

Big Baby's Bird & Tackle


COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT
SOURCE



HISTORIC
INFO

Was at one time C. P. Coal Company. Additional permits:
#9376 (1942)--remodel office (\$400); B91-236 (1991)--siding

LANDSCAPE

Concrete & asphalt apron; parking
on west side; drive to rear storage lot
and access to rear addition

PHOTO INFORMATION

ROLL1

3

FRAMES1

1

ROLL2

11

FRAMES2

15-16

ROLL3

FRAMES3

DIGITAL
PHOTO ID

e:\morgan0154.j
pg

SURVEY INFORMATION

PREPARER

VICKI GRANACKI

PREPARER
ORGANIZATION

GRANACKI HISTORIC
CONSULTANTS

SURVEYDATE

3/17/2005

SURVEYAREA

Barber-Colman


City of ROCKFORD

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY CONTINUATION SHEET

STREET # 154

STREET MORGAN ST

ADDITIONAL PHOTOS OR INFORMATION



STREET #

DIRECTION

STREET

ABB

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

| | | | |
|----------------------|--|-------------------------|---|
| CATEGORY | <input type="text" value="building"/> | CURRENT FUNCTION | <input type="text" value="Industry/Processing/Extraction"/> |
| CONDITION | <input type="text" value="fair"/> | HISTORIC FUNCTION | <input type="text" value="Industry/Processing/Extraction"/> |
| INTEGRITY | <input type="text" value="minor alterations and addition(s)"/> | REASON for SIGNIFICANCE | <input type="text"/> |
| STOREFRONT INTEGRITY | <input type="text"/> | | |
| SECONDARY STRUCTURE | <input type="text"/> | | |

ARCHITECTURAL DESCRIPTION

| | | | |
|------------------------------|---|-----------------|--|
| ARCHITECTURAL CLASSIFICATION | <input type="text" value="Industrial - Storage"/> | PLAN | <input type="text" value="rectangular"/> |
| DETAILS | <input type="text"/> | NO OF STORIES | <input type="text" value="1"/> |
| BEGINYEAR | <input type="text" value="c. 1925"/> | ROOF TYPE | <input type="text" value="Flat"/> |
| OTHER YEAR | <input type="text"/> | ROOF MATERIAL | <input type="text" value="Not visible"/> |
| DATESOURCE | <input type="text" value="Surveyor"/> | FOUNDATION | <input type="text" value="Concrete - poured"/> |
| WALL MATERIAL (current) | <input type="text" value="Brick"/> | PORCH | <input type="text" value="Full front"/> |
| WALL MATERIAL 2 (current) | <input type="text" value="Common Brick"/> | WINDOW MATERIAL | <input type="text" value="Boarded"/> |
| WALL MATERIAL (original) | <input type="text" value="Brick"/> | WINDOW MATERIAL | <input type="text" value="Wood"/> |
| WALL MATERIAL 2 (original) | <input type="text" value="Common Brick"/> | WINDOW TYPE | <input type="text" value="double hung"/> |
| | | WINDOW CONFIG | <input type="text" value="1/1"/> |

SIGNIFICANT FEATURES

ALTERATIONS

**STOREFRONT
FEATURES**

**STOREFRONT
ALTERATIONS**

Building permits: permit #4680 (1931)--remove old building and remodel front hall; remodel [Permit #4768 (1931)]; install new ceiling joists [Permit #19944 (1955)]; remodel masonry garage & install new overhead door [Permit #21690 (1959)]

HISTORIC INFORMATION

**HISTORIC
NAME**

**COMMON
NAME**

COST

ARCHITECT

ARCHITECT2

BUILDER

**ARCHITECT
SOURCE**

**HISTORIC
INFO**

LANDSCAPE

Southeast corner of River and Morgan; concrete parking pad at front; chain link fence around lot to east

PHOTO INFORMATION

ROLL1

3

FRAMES1

2

ROLL2

FRAMES2

ROLL3

FRAMES3

**DIGITAL
PHOTO ID**

e:\morgan0158.jpg

SURVEY INFORMATION

PREPARER

JENNIFER KENNY

**PREPARER
ORGANIZATION**

GRANACKI HISTORIC
CONSULTANTS

SURVEYDATE

3/17/2005

SURVEYAREA

Barber-Colman

STREET #

DIRECTION

STREET

ABB

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT
FEATURES

STOREFRONT
ALTERATIONS

HISTORIC INFORMATION

HISTORIC
NAME

COMMON
NAME

Martin's Auto Repair

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT
SOURCE

HISTORIC
INFO

LANDSCAPE

Adjacent to RR tracks on east;
parking lot to west; concrete
sidewalk in front; gravel apron; no
curb

PHOTO INFORMATION

ROLL1

3

FRAMES1

3

ROLL2

FRAMES2

ROLL3

FRAMES3

DIGITAL
PHOTO ID

e:\morgan0175.j
pg

SURVEY INFORMATION

PREPARER

VICKI GRANACKI

PREPARER
ORGANIZATION

GRANACKI HISTORIC
CONSULTANTS

SURVEYDATE

3/17/2005

SURVEYAREA

Barber-Colman

STREET #

DIRECTION

STREET

ABB

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS

BEGIN YEAR NO OF STORIES

OTHER YEAR ROOF TYPE

DATE SOURCE ROOF MATERIAL

FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT
FEATURES

STOREFRONT
ALTERATIONS

HISTORIC INFORMATION

HISTORIC
NAME

COMMON
NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT
SOURCE

HISTORIC
INFO

LANDSCAPE

Southeast corner of Rock & Morgan;
building angled on lot; asphalt
driveway at front; curb cuts at both
streets

PHOTO INFORMATION

ROLL1

FRAMES1

ROLL2

FRAMES2

ROLL3

FRAMES3

DIGITAL
PHOTO ID

SURVEY INFORMATION

PREPARER

PREPARER
ORGANIZATION

SURVEYDATE

SURVEYAREA

City of ROCKFORD

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY CONTINUATION SHEET

STREET # 178

STREET MORGAN ST

ADDITIONAL PHOTOS AND INFORMATION

Permit information

#4907-4908 (1925)—1 metal oil service station & 1 metal oil storage building; #19373 (1951)—25x30 cement block service station;

Alterations

Replacement overhead garage doors in original openings and also some enclosed [#44321 (1974)—remove overhead doors and block up with masonry]; wood vertical cladding added to southwest end [permit #46267 (1976)—remove plate glass windows and close same]; #21756 (1959)—23x30 addition to fill in between existing buildings; large overhanging roof added (non-historic)

STREET #

DIRECTION

STREET

ABB

PIN

LOCAL SIGNIFICANCE RATING


POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

STOREFRONT INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS

BEGINYEAR NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATIONS

PORCH

WALL MATERIAL (current) WINDOW MATERIAL

WALL MATERIAL 2 (current)

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

STOREFRONT
FEATURES

[Empty box for Storefront Features]

STOREFRONT
ALTERATIONS

[Empty box for Storefront Alterations]

HISTORIC INFORMATION

HISTORIC
NAME

[Empty box for Historic Name]

COMMON
NAME

P & W Supply Co.

COST

[Empty box for Cost]

ARCHITECT

Carpenter, Frank

ARCHITECT2

[Empty box for Architect2]

BUILDER

Security Building Co.

ARCHITECT
SOURCE

Building Permit

[Large empty box for Historic Information]

HISTORIC
INFO

See continuation sheet for building permits.

LANDSCAPE

Northwest corner lot; concrete and asphalt apron with parking on east side; gravel lot to west

PHOTO INFORMATION

ROLL1

3

FRAMES1

5

ROLL2

[Empty box for Roll2]

FRAMES2

[Empty box for Frames2]

ROLL3

[Empty box for Roll3]

FRAMES3

[Empty box for Frames3]

DIGITAL
PHOTO ID

e:\morgan0203.j
pg

SURVEY INFORMATION

PREPARER

VICKI GRANACKI

PREPARER
ORGANIZATION

GRANACKI HISTORIC
CONSULTANTS

SURVEYDATE

3/17/2005

SURVEYAREA

Barber-Colman

City of ROCKFORD

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY CONTINUATION SHEET

STREET # 203

STREET MORGAN ST

ADDITIONAL PHOTOS AND INFORMATION

Permit information:

#9726 (1928)—masonry public garage; #5720 (1935)—ice box—partition and remodel;
#6226 (1936)—remodel 1st floor for office; #6454 (1937)—16x28 refrigerator; #7866

Permits listed for 203 Morgan but are now 1025 Rock: (1940)—1 story rear addition (10x19); #10927 (1945)—one story cement block addition (40x70) to enlarge garage storage; #11032 (1946)—one story cement block addition to warehouse (36x75)

STREET #

DIRECTION

STREET

ABB

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

CRITERIA

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

| | | | |
|----------------------|--|-------------------------|--|
| CATEGORY | <input type="text" value="building"/> | CURRENT FUNCTION | <input type="text" value="Commerce/Trade - business"/> |
| CONDITION | <input type="text" value="good"/> | HISTORIC FUNCTION | <input type="text" value="Commerce/Trade - business"/> |
| INTEGRITY | <input type="text" value="minor alterations and addition(s)"/> | REASON for SIGNIFICANCE | <input type="text" value="Notable Two Part Commercial Block with interesting brickwork and arched parapet, together with distinctive corner storefront entry."/> |
| STOREFRONT INTEGRITY | <input type="text" value="Minor alterations"/> | | |
| SECONDARY STRUCTURE | <input type="text"/> | | |

ARCHITECTURAL DESCRIPTION

| | | | |
|------------------------------|--|-----------------|--|
| ARCHITECTURAL CLASSIFICATION | <input type="text" value="Two Part Commercial Block"/> | PLAN | <input type="text" value="rectangular"/> |
| DETAILS | <input type="text"/> | NO OF STORIES | <input type="text" value="2"/> |
| BEGINYEAR | <input type="text" value="c. 1910"/> | ROOF TYPE | <input type="text" value="Flat"/> |
| OTHER YEAR | <input type="text"/> | ROOF MATERIAL | <input type="text" value="Not visible"/> |
| DATESOURCE | <input type="text" value="Surveyor"/> | FOUNDATION | <input type="text" value="Concrete - poured"/> |
| WALL MATERIAL (current) | <input type="text" value="Brick"/> | PORCH | <input type="text"/> |
| WALL MATERIAL 2 (current) | <input type="text"/> | WINDOW MATERIAL | <input type="text" value="Wood"/> |
| WALL MATERIAL (original) | <input type="text" value="Brick"/> | WINDOW MATERIAL | <input type="text"/> |
| WALL MATERIAL 2 (original) | <input type="text"/> | WINDOW TYPE | <input type="text" value="double hung"/> |
| | | WINDOW CONFIG | <input type="text" value="1/1"/> |

SIGNIFICANT FEATURES

ALTERATIONS

**STOREFRONT
FEATURES**

Stone frieze above storefront level; recessed corner entry with wood paneled door on angle; historic wood display windows w/ prism glass transoms; central entry to second floor; prism glass transom over doorway

**STOREFRONT
ALTERATIONS**

One display window opening blocked in

HISTORIC INFORMATION

**HISTORIC
NAME**

**COMMON
NAME**

COST

ARCHITECT

ARCHITECT2

BUILDER

**ARCHITECT
SOURCE**



**HISTORIC
INFO**

See continuation sheet for building permits.

LANDSCAPE

Midblock on south side of street; adjacent to alley on the west; lot slopes to the east; no setback; concrete sidewalk and driveway on east

PHOTO INFORMATION

ROLL1

FRAMES1

ROLL2

FRAMES2

ROLL3

FRAMES3

**DIGITAL
PHOTO ID**

SURVEY INFORMATION

PREPARER

**PREPARER
ORGANIZATION**

SURVEYDATE

SURVEYAREA

City of ROCKFORD

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY CONTINUATION SHEET

STREET # 308

STREET MORGAN ST.

ADDITIONAL PHOTOS AND INFORMATION

Permit information:

****Listed under 308 Morgan Street and 308-310 Morgan Street****

308 Morgan Street

#21191 (3/31/1953)—24x48-4 Aluminum bottling works

308-310 Morgan Street

#6397 (1937)—new concrete floor; #2366 (1961)—south side addition (approx. 70x60) for storage

This is to CERTIFY that the images appearing on this film are ACTUAL, ACCURATE AND COMPLETE REPRODUCTIONS of the records of THE CITY OF ROCKFORD BUILDING DEPARTMENT and are created in the normal course of business.


J. Shuman 8, 12, 92
CAMERA OPERATOR DATE

#7

#3101 MAM + VAR.

310 Morgan St

308-10 MORGAN ST.



Plot Plan & Bldg. Sketch.