City of ROCKFORD - Commercial/Industrial

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY

STREET #	1101-1103
DIRECTION	S
STREET	MAIN
ABB	ST
PIN	11-27-277-009
LOCAL SIGNIFICANCE RATING	NC
POTENTIAL IND NR? (Y or N)	N
CRITERIA	
Contributing to a NR DISTRICT?	NC
Contributing secondary structure?	-
Listed on existing SURVEY?	SM; RHPC



GENERAL INFORMATION

CATEGORY	building	CURRENT FUNCTION	Vacant/Not in Use
CONDITION	fair	HISTORIC FUNCTION	Transportation - gas station
INTEGRITY	major alterations and/or addition(s)	REASON for SIGNFICANCE	
STOREFRONT INTEGRITY	minor alterations		
SECONDARY STRUCTURE			

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Gas Station	PLAN	rectangular
DETAILS		NO OF STORIES	1
BEGINYEAR	1939	ROOF TYPE	Flat
OTHER YEAR	1965	ROOF MATERIAL	Not visible
DATESOURCE	building permit	FOUNDATION	Concrete - poured
WALL MATERIAL (current)	Stone veneer	PORCH	
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Plate Glass
WALL MATERIAL (original)	Brick	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	display
		WINDOW CONFIG	

SIGNIFICANT FEATURES	Curved wall at north end with curved entry and 4 windows; central wood entry door with one-light transom above; ceramic tile coping
ALTERATIONS	See continuation sheet

STOREFRONT FEATURES	See above
STOREFRONT ALTERATIONS	

HISTORIC INFORMATION

HISTORIC NAME	Standard Oil Gas Station
COMMON NAME	
COST	4000
ARCHITECT	
ARCHITECT2	
BUILDER	Standard Oil Company
ARCHITECT SOURCE	



HISTORIC INFO	Original permit -- #12773 (10/6/1939)--1 story brick service station & garage	**LANDSCAPE**	Commercial uses on busy 4-lane highway; asphalt drive at front; building setback 25 feet; concrete retaining wall at sidewalk

PHOTO INFORMATION

ROLL1	2
FRAMES1	8
ROLL2	
FRAMES2	
ROLL3	
FRAMES3	
DIGITAL PHOTO ID	e:\main1101-1103s.jpg

SURVEY INFORMATION

PREPARER	JENNIFER KENNY
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	3/8/2005
SURVEYAREA	Barber-Colman

City of ROCKFORD

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY
CONTINUATION SHEET

STREET # 1101 - 1103

STREET S. MAIN ST

ADDITIONAL PHOTOS OR INFORMATION

Alterations

stone veneer cladding with weeping mortar over entire facade; brick parapet walls for planter boxes; formerly 2 garage bays, now blocked in and covered with stone veneer; garage entry door with boarded-in transom [Permit #18962 (1956)--general remodel ($5000); permit #28815 (1965)--general repairs & renew front]

City of ROCKFORD - Commercial/Industrial

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY

STREET #	1108
DIRECTION	S
STREET	MAIN
ABB	ST
PIN	11-27-280-002
LOCAL SIGNIFICANCE RATING	NC
POTENTIAL IND NR? (Y or N)	N
CRITERIA	
Contributing to a NR DISTRICT?	NC
Contributing secondary structure?	-
Listed on existing SURVEY?	SM; RHPC

GENERAL INFORMATION

CATEGORY	building	CURRENT FUNCTION	Commerce/Trade - business
CONDITION	fair	HISTORIC FUNCTION	Commerce/Trade - business
INTEGRITY	major alterations and/or addition(s)	REASON for SIGNFICANCE	
STOREFRONT INTEGRITY	major alterations		
SECONDARY STRUCTURE			

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Two Part Commercial Block	PLAN	rectangular
DETAILS		NO OF STORIES	2
BEGINYEAR	c. 1910	ROOF TYPE	Flat
OTHER YEAR	1950s	ROOF MATERIAL	Not visible
DATESOURCE	Main Street Survey	FOUNDATION	Concrete - poured
WALL MATERIAL (current)	Brick	PORCH	
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Aluminum
WALL MATERIAL (original)	Brick	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	casement/fixed
		WINDOW CONFIG	single pane; multi-pane

SIGNIFICANT FEATURES	
ALTERATIONS	Modern facade added to original building, obscuring original facade (c. 1950s); Non-historic aluminum casement windows on front facade; rear addition

STOREFRONT FEATURES	
STOREFRONT ALTERATIONS	Original storefront has been extensively altered [#20939 (1959)--install new store front]; Aluminum display windows and entry; non-historic wood canopy over entire storefront

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	Listed in permit file as 1108-1110 1/2--see continuation sheet for 1108 for permits for 1108, 1110, & 1110 1/2	**LANDSCAPE**	midblock on east corner of busy 4 lane highway; parking lot to north of building; party wall on south side

PHOTO INFORMATION

ROLL1	2
FRAMES1	10
ROLL2	
FRAMES2	
ROLL3	
FRAMES3	
DIGITAL PHOTO ID	e:\main1108s.jpg

SURVEY INFORMATION

PREPARER	LARA RAMSEY
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	3/8/2005
SURVEYAREA	Barber-Colman

City of ROCKFORD

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY
CONTINUATION SHEET

STREET # 1108

STREET S MAIN ST

ADDITIONAL PHOTOS AND INFORMATION

Permit information:

1108 S. Main Street
#958 (1943)–repair fire loss; #11235 (1948)–enclose front stairway; #20939 (1959)–install new store front

1110 S. Main Street
#647 (1923)–addition and remodel; #1316 (1922)–16x60 2nd story addition to present one story building; #3763 (1926)–remodel; #4635 (1930)–chimney; #46579 (1976)–remove fallen porch roof and block off stairs

1110 ½ S. Main Street
No permits.

1108-1112 S. Main Street Permits
B82-722 (1982)--18' high concrete block wall around courtyard

City of ROCKFORD - Commercial/Industrial

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY

STREET #	1112
DIRECTION	S
STREET	MAIN
ABB	ST
PIN	11-27-280-003
LOCAL SIGNIFICANCE RATING	NC
POTENTIAL IND NR? (Y or N)	N
CRITERIA	
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	-
Listed on existing SURVEY?	SM; RHPC

GENERAL INFORMATION

CATEGORY	building	**CURRENT FUNCTION**	Commerce/Trade - business
CONDITION	fair	**HISTORIC FUNCTION**	Commerce/Trade - business
INTEGRITY	major alterations and/or addition(s)	**REASON for SIGNFICANCE**	
STOREFRONT INTEGRITY	major alterations		
SECONDARY STRUCTURE			

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Two Part Commercial Block	**PLAN**	rectangular
DETAILS		**NO OF STORIES**	2
BEGINYEAR	c. 1915	**ROOF TYPE**	Flat
OTHER YEAR		**ROOF MATERIAL**	Not visible
DATESOURCE	Main Street Survey	**FOUNDATION**	Concrete - poured
WALL MATERIAL (current)	Brick	**PORCH**	
WALL MATERIAL 2 (current)		**WINDOW MATERIAL**	Aluminum
WALL MATERIAL (original)	Brick	**WINDOW MATERIAL**	
WALL MATERIAL 2 (original)		**WINDOW TYPE**	double hung/fixed
		WINDOW CONFIG	1/1; single pane

SIGNIFICANT FEATURES	front facade with blonde brick; corbelled brick cornice; brick hatch work pattern running across facade below cornice; stone sills on 2nd store windows
ALTERATIONS	rear addition [#1518 (1923)–14x10 masonry rear addition]; replacement windows in original openings on 2nd story

STOREFRONT FEATURES	Storefronts have been completely altered
STOREFRONT ALTERATIONS	several display window openings and door openings blocked in; transoms over windows and doors covered; new entry to upper level at north end of facade; Aluminum replacement windows and doors

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	; #1695 (1923)–16x24 addition (basement & 1 story); #11910 (1947)–raise roof over garage (see also continuation sheet for 1108-1110 1/2 S. Main)
LANDSCAPE	midblock on east side of busy 4-lane highway; party walls on north and south sides of building

PHOTO INFORMATION

ROLL1	2
FRAMES1	1
ROLL2	
FRAMES2	
ROLL3	
FRAMES3	
DIGITAL PHOTO ID	e:\main1112s.jpg

SURVEY INFORMATION

PREPARER	LARA RAMSEY
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	3/8/2005
SURVEYAREA	Barber-Colman

City of ROCKFORD - Commercial/Industrial

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY

STREET #	1115
DIRECTION	S
STREET	MAIN
ABB	ST
PIN	11-27-277-011
LOCAL SIGNIFICANCE RATING	S
POTENTIAL IND NR? (Y or N)	Y
CRITERIA	A,C
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	SM; IHSS; NRHP

GENERAL INFORMATION

CATEGORY	building	CURRENT FUNCTION	Museum
CONDITION	excellent	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations and addition(s)	REASON for SIGNFICANCE	
STOREFRONT INTEGRITY			
SECONDARY STRUCTURE	coach house		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Italianate	PLAN	rectangular
DETAILS		NO OF STORIES	2
BEGINYEAR	1857	ROOF TYPE	Front gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	S. Main Street Survey/NR	FOUNDATION	Stone
WALL MATERIAL (current)	Stone	PORCH	
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Stone	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung
		WINDOW CONFIG	1/1

SIGNIFICANT FEATURES	Ashlar stone exterior; scrolled brackets in eaves; wood paneled frieze; front entry porch with gable roof and exaggerated scrolled supports; saw tooth and scroll molding; wood front entry door with stained glass transom smooth stone sills and lintels
ALTERATIONS	See continuation sheet

STOREFRONT FEATURES	
STOREFRONT ALTERATIONS	

HISTORIC INFORMATION

HISTORIC NAME	Graham-Ginestra House
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	Placed on National Register 1979; Built for Freeman Graham, owner of the first sour mash distillery in the state. Secondary structures include stone privy (?) and frame coach house with garage (both rated "C"). See continuation sheet for permits.
LANDSCAPE	Middle of mixed-use block on west side of 4-lane highway; wood fencing at front with stone piers; large lot to south with concrete driveway; fence continues to south. PIN #11-27-277-012 (1123 S. Main) is part of property.

PHOTO INFORMATION

ROLL1	2
FRAMES1	11
ROLL2	
FRAMES2	
ROLL3	
FRAMES3	
DIGITAL PHOTO ID	e:\main1115s.jpg

SURVEY INFORMATION

PREPARER	JENNIFER KENNY
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	3/8/2005
SURVEYAREA	Barber-Colman

City of ROCKFORD

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY
CONTINUATION SHEET

STREET # 1115

STREET S MAIN ST

ADDITIONAL PHOTOS OR INFORMATION

Alterations

Aluminum storm windows, door; stone appears to have been power washed; partially in filled front entry; stained glass window on side not original; building to north is attached, one story brick and concrete block garage [#33016 (1968)–9x25 concrete block addition to north side of garage]; rear, non-historic, one story garage addition has been converted to room [#14943 (1952)–20x20 cement block one story addition for utility room & garage to west of residence]

ADDITIONAL PERMIT INFORMATION

#4028 (1933)–new cornice work; #B80-762 (1980)–restoration/repair of outbuildings

City of ROCKFORD - Commercial/Industrial

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY

STREET #	1118
DIRECTION	S
STREET	MAIN
ABB	ST
PIN	11-27-280-004
LOCAL SIGNIFICANCE RATING	NC
POTENTIAL IND NR? (Y or N)	N
CRITERIA	
Contributing to a NR DISTRICT?	NC
Contributing secondary structure?	-
Listed on existing SURVEY?	SM



GENERAL INFORMATION

CATEGORY	building	CURRENT FUNCTION	Commerce/Trade - business
CONDITION	fair	HISTORIC FUNCTION	Commerce/Trade - business
INTEGRITY	major alterations and/or addition(s)	REASON for SIGNFICANCE	
STOREFRONT INTEGRITY	major alterations		
SECONDARY STRUCTURE			

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	One Part Commercial Block	PLAN	rectangular
DETAILS		NO OF STORIES	1
BEGINYEAR	1949	ROOF TYPE	Flat
OTHER YEAR		ROOF MATERIAL	Not visible
DATESOURCE	Main Street Survey	FOUNDATION	Concrete - poured
WALL MATERIAL (current)	Brick	PORCH	
WALL MATERIAL 2 (current)	Stone	WINDOW MATERIAL	Aluminum
WALL MATERIAL (original)	Stone	WINDOW MATERIAL	
WALL MATERIAL 2 (original)	Concrete	WINDOW TYPE	fixed
		WINDOW CONFIG	single pane

SIGNIFICANT FEATURES	original 1949 building was a combination of steel, concrete, and stone [according to 1997 S. Main Street survey]
ALTERATIONS	addition [1952--according to 1997 South Main Street Survey]

STOREFRONT FEATURES	
STOREFRONT ALTERATIONS	current storefront with vertical board siding [permit B89-559 (1989)--replacing boards in front of building and painting exterior]; stone veneer and angled entrance at north end built in 1987 [according to 1997 South Main Street Survey]

HISTORIC INFORMATION

HISTORIC NAME	Al-Mar Florist
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	
LANDSCAPE	midblock on east side of 4-lane highway; party walls on north and south sides of building

PHOTO INFORMATION

ROLL1	2
FRAMES1	2
ROLL2	
FRAMES2	
ROLL3	
FRAMES3	
DIGITAL PHOTO ID	e:\main1118s.jpg

SURVEY INFORMATION

PREPARER	LARA RAMSEY
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	3/8/2005
SURVEYAREA	Barber-Colman

City of ROCKFORD - Commercial/Industrial

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY

STREET #	1122
DIRECTION	S
STREET	MAIN
ABB	ST
PIN	11-27-280-005
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
CRITERIA	
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	-
Listed on existing SURVEY?	SM; IHSS

GENERAL INFORMATION

CATEGORY	building	CURRENT FUNCTION	Commerce/Trade - business
CONDITION	deteriorated	HISTORIC FUNCTION	Recreation and Culture - theater
INTEGRITY	major alterations and/or addition(s)	REASON for SIGNFICANCE	may have once been architecturally significant, but there are too many alterations now
STOREFRONT INTEGRITY	major alterations		
SECONDARY STRUCTURE			

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Theater/Spanish Baroque	PLAN	rectangular
DETAILS		NO OF STORIES	2
BEGINYEAR	1928	ROOF TYPE	Flat
OTHER YEAR		ROOF MATERIAL	Not visible
DATESOURCE	South Main Street Survey	FOUNDATION	Concrete - poured
WALL MATERIAL (current)	Brick	PORCH	
WALL MATERIAL 2 (current)	Stone	WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Brick	WINDOW MATERIAL	Aluminum
WALL MATERIAL 2 (original)	Stone	WINDOW TYPE	double hung/fixed
		WINDOW CONFIG	1/1; diamond; multi-pane

SIGNIFICANT FEATURES	See continuation sheet
ALTERATIONS	See continuation sheet

STOREFRONT FEATURES	See continuation sheet
STOREFRONT ALTERATIONS	See continuation sheet

HISTORIC INFORMATION

HISTORIC NAME	Capital Theatre
COMMON NAME	
COST	
ARCHITECT	Van Der Meer, Wybe J.
ARCHITECT2	MS (1997)
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	
LANDSCAPE	midblock on east side of 4-lane highway; party walls on north and south sides of building

PHOTO INFORMATION

ROLL1	2
FRAMES1	3-4
ROLL2	
FRAMES2	
ROLL3	
FRAMES3	
DIGITAL PHOTO ID	e:\main1122s.jpg

SURVEY INFORMATION

PREPARER	LARA RAMSEY
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	3/8/2005
SURVEYAREA	Barber-Colman

City of ROCKFORD

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY
CONTINUATION SHEET

STREET # 1122

STREET S MAIN ST

ADDITIONAL PHOTOS OR INFORMATION

Significant Features

Building consists of a center section (which originally housed the theater entrance) flanked by two identical wings; the center section features four stone and terra cotta face medallions above 2nd floor windows, portions of stone parapet with arches, a series of four double hung 2nd story windows separated by roped pilasters, and arched terra cotta (stone?) lintels with a shell motif on all 2nd floor windows; the north and south wings each feature roofs covered with ceramic tiles, underneath which are rows of unadorned windows; the north and south wings terminate with a single bay topped with a broken pediment parapet, with terra cotta (stone?) cartouches, scrolls, and window lintels

Alterations

Theater entrance section of building has been extensively altered–the triangulated pediment has been removed, and the marquee and vertical sign have been removed, with the wall underneath patched with common brick; some trim missing; non-historic iron balconets on all 2nd floor windows; replacement windows in original openings

Storefront Features

Originally a center theater entrance with two storefronts on each side; all storefront feature original configuration of an angled, recessed center entrance with display windows on each side (the only storefront that varies from this pattern is the south storefront, which features a recessed side entrance with a display window on its north side–this original configuration allows for the main entrance to the upper level, located in the southernmost bay of the building); terra cotta surround at theater entrance remains; prism glass transoms above northern most storefront with floral pattern; tile floors in entryways to all storefronts; historic metal window trim

Storefront Alterations

Transoms on all but north storefront are either covered or removed; terra cotta bulkhead covered with siding with brick pattern; entrance to theater altered–angled vertical board front with double doors at south (right) end of entrance and two windows

at north end; display windows on storefront just south of theater entrance downsized with vertical board

City of ROCKFORD - Commercial/Industrial

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY

STREET #	1128
DIRECTION	S
STREET	MAIN
ABB	ST
PIN	11-27-280-006
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
CRITERIA	
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	-
Listed on existing SURVEY?	SM; RHPC

GENERAL INFORMATION

CATEGORY	building	**CURRENT FUNCTION**	Commerce/Trade - business
CONDITION	fair	**HISTORIC FUNCTION**	Commerce/Trade - business
INTEGRITY	minor alterations	**REASON for SIGNFICANCE**	
STOREFRONT INTEGRITY	major alterations		
SECONDARY STRUCTURE			

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Two Part Commercial Block	**PLAN**	rectangular
DETAILS		**NO OF STORIES**	2
BEGINYEAR	1918	**ROOF TYPE**	Flat
OTHER YEAR		**ROOF MATERIAL**	Not visible
DATESOURCE	Date panel on building	**FOUNDATION**	Stone
WALL MATERIAL (current)	Brick	**PORCH**	
WALL MATERIAL 2 (current)	Stone	**WINDOW MATERIAL**	Wood
WALL MATERIAL (original)	Brick	**WINDOW MATERIAL**	Aluminum
WALL MATERIAL 2 (original)	Stone	**WINDOW TYPE**	double hung/fixed
		WINDOW CONFIG	1/1; 6/1; single pane

SIGNIFICANT FEATURES	See continuation sheet
ALTERATIONS	Some aluminum replacement windows in original openings on both facades

STOREFRONT FEATURES	Brick square piers with stone detailing at tops; 1 storefront with recessed corner entrance; original tile floor in front of door; main entrance to upper floor at north end of front facade
STOREFRONT ALTERATIONS	See continuation sheet

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	Additional permits -- B84-1327 (1984)--new back porch
LANDSCAPE	northeast corner of Loomis and S. Main; party wall on north side of building

PHOTO INFORMATION

ROLL1	2
FRAMES1	5
ROLL2	
FRAMES2	
ROLL3	
FRAMES3	
DIGITAL PHOTO ID	e:\main1128s.jpg

SURVEY INFORMATION

PREPARER	LARA RAMSEY
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	3/8/2005
SURVEYAREA	Barber-Colman

City of ROCKFORD

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY
CONTINUATION SHEET

STREET # 1128

STREET S MAIN ST

ADDITIONAL PHOTOS OR INFORMATION

Significant Features

3 bay front facade with polychromatic brickwork; brick parapet with date panel in center on front facade; corbeled brick cornice; thin string course above upper windows; 8 bay south facade with stepped parapet; paired 6/1 windows on 1st and 2nd stories on south facade

Storefront Alterations

substantial changes to storefront[#8937 (1979)--remodel]--entire storefront has been covered with vertical board siding pierced with high, fixed pane windows; the transom areas along the storefront and above the entrance have also been covered with vertical paneling; main entrance to upper level boarded up

City of ROCKFORD - Commercial/Industrial

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY

STREET #	1129
DIRECTION	S
STREET	MAIN
ABB	ST
PIN	11-27-277-013
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
CRITERIA	
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	NC
Listed on existing SURVEY?	SM; RHPC



GENERAL INFORMATION

CATEGORY	building	CURRENT FUNCTION	Museum
CONDITION	fair	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations and addition(s)	REASON for SIGNFICANCE	
STOREFRONT INTEGRITY			
SECONDARY STRUCTURE	gazebo		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Upright and Wing	PLAN	L
DETAILS	Greek Revival	NO OF STORIES	1
BEGINYEAR	c. 1855	ROOF TYPE	Cross Gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	S. Main Street Survey	FOUNDATION	Stone
WALL MATERIAL (current)	Aluminum siding	PORCH	Front
WALL MATERIAL 2 (current)	Stone	WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	
WALL MATERIAL 2 (original)	Stone	WINDOW TYPE	double hung
		WINDOW CONFIG	4/4

SIGNIFICANT FEATURES	Stone exterior and sills; original 2/2 wood double hung windows with wood storms; wood front porch across wing portion
ALTERATIONS	See continuation sheet

STOREFRONT FEATURES	
STOREFRONT ALTERATIONS	

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	
LANDSCAPE	Alt. Address -- 305 Loomis; mixed uses on west side of four lane state highway; NW corner of Loomis and S. Main; asphalt parking lot; wood picket fence surrounds property; one mature tree; lot slopes upward from rear

PHOTO INFORMATION

ROLL1	2
FRAMES1	12-13
ROLL2	
FRAMES2	
ROLL3	
FRAMES3	
DIGITAL PHOTO ID	e:\main1129s.jpg

SURVEY INFORMATION

PREPARER	JENNIFER KENNY
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	3/8/2005
SURVEYAREA	Barber-Colman

City of ROCKFORD

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY
CONTINUATION SHEET

STREET # 1129

STREET S MAIN ST

ADDITIONAL PHOTOS OR INFORMATION

Alterations

Aluminum siding on upright portion; non historic additional entry and stoop on north facade (likely an enlarged window opening); missing front porch rail and replacement wood supports and brackets [#B88-940 (1988)--repair porch]; 1 story brick rear wing (historic) and addition frame rear wing addition with Aluminum siding; wood vertical siding on rear

City of ROCKFORD - Commercial/Industrial

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY

STREET #	1207
DIRECTION	S
STREET	MAIN
ABB	ST
PIN	11-27-278-016
LOCAL SIGNIFICANCE RATING	NC
POTENTIAL IND NR? (Y or N)	N
CRITERIA	
Contributing to a NR DISTRICT?	NC
Contributing secondary structure?	-
Listed on existing SURVEY?	

GENERAL INFORMATION

CATEGORY	building	**CURRENT FUNCTION**	Commerce/Trade - business
CONDITION	excellent	**HISTORIC FUNCTION**	Commerce/Trade - business
INTEGRITY	not altered	**REASON for SIGNFICANCE**	
STOREFRONT INTEGRITY	not altered		
SECONDARY STRUCTURE			

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Strip Mall	**PLAN**	rectangular
DETAILS		**NO OF STORIES**	1
BEGINYEAR	1990s	**ROOF TYPE**	Front gable
OTHER YEAR		**ROOF MATERIAL**	Not visible
DATESOURCE	Surveyor	**FOUNDATION**	Concrete - poured
WALL MATERIAL (current)	Brick veneer	**PORCH**	
WALL MATERIAL 2 (current)	Aluminum	**WINDOW MATERIAL**	Aluminum
WALL MATERIAL (original)	Brick veneer	**WINDOW MATERIAL**	
WALL MATERIAL 2 (original)	Aluminum	**WINDOW TYPE**	?
		WINDOW CONFIG	

SIGNIFICANT FEATURES	entry doors off of parking lot to north at center of north facade and at west end on east facade
ALTERATIONS	

STOREFRONT FEATURES	
STOREFRONT ALTERATIONS	

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	Spin World Laundromat Lavendaria
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	
LANDSCAPE	On west side of four lane state highway; mixed use block; parking lot to north; building built on rise above street; concrete steps and retaining wall at front

PHOTO INFORMATION

ROLL1	2
FRAMES1	14
ROLL2	
FRAMES2	
ROLL3	
FRAMES3	
DIGITAL PHOTO ID	e:\main1207s.jpg

SURVEY INFORMATION

PREPARER	JENNIFER KENNY
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	3/8/2005
SURVEYAREA	Barber-Colman

City of ROCKFORD

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY
CONTINUATION SHEET

STREET # 1207

STREET S MAIN ST

ADDITIONAL PHOTOS AND INFORMATION

Permit information:

****Listed in permit file as 1203 & 1209 S. Main Street****

1203 S. Main Street

#39126 (1972)–demolish one-family residence

1209 S. Main Street

B80-433 (1980)–demolish single family residence; Drawings for proposed banquet hall with parking lot

City of ROCKFORD - Commercial/Industrial

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY

STREET #	1213
DIRECTION	S
STREET	MAIN
ABB	ST
PIN	11-27-278-010
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
CRITERIA	
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	-
Listed on existing SURVEY?	SM; RHPC

GENERAL INFORMATION

CATEGORY	building	CURRENT FUNCTION	Domestic - multiple dwelling
CONDITION	fair	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations and addition(s)	REASON for SIGNFICANCE	
STOREFRONT INTEGRITY			
SECONDARY STRUCTURE			

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Victorian Gothic Revival	PLAN	irregular
DETAILS	Eastlake	NO OF STORIES	2.5
BEGINYEAR	c. 1885	ROOF TYPE	Gable on hip
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Limestone
WALL MATERIAL (current)	Wood	PORCH	Full Front
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung
		WINDOW CONFIG	1/1

SIGNIFICANT FEATURES	Historic full width front porch with concrete block piers, knee wall, and rails; projecting window bay on front replicated bargeboards in front, north, and south gables; decorative round window on north side; replicated Eastlake wood window hoods
ALTERATIONS	See continuation sheet

STOREFRONT FEATURES	
STOREFRONT ALTERATIONS	

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	Additional permits -- #6592 (193?)--rebuild garage out of old barn; #43720 (1937)--closing door openings & plastering
LANDSCAPE	house faces east on mixed use block of four lane state highway; house built on rise; wood fence; concrete retaining wall at front with concrete steps

PHOTO INFORMATION

ROLL1	2
FRAMES1	15
ROLL2	
FRAMES2	
ROLL3	
FRAMES3	
DIGITAL PHOTO ID	e:\main1213s.jpg

SURVEY INFORMATION

PREPARER	JENNIFER KENNY
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	3/8/2005
SURVEYAREA	Barber-Colman

City of ROCKFORD

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY
CONTINUATION SHEET

STREET # 1213

STREET S MAIN ST

ADDITIONAL PHOTOS OR INFORMATION

Alterations

10' x 14' south side addition [permit #10477 (1944)--2 story south addition]; front porch probably added at same time; downsized front entry; enclosed front attic window; shutters added; 2 story front addition at south end (may be historic); 2 story rear addition (historic)

City of ROCKFORD - Commercial/Industrial

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY

STREET #	1215
DIRECTION	S
STREET	MAIN
ABB	ST
PIN	11-27-278-011
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
CRITERIA	
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	-
Listed on existing SURVEY?	SM; RHPC



GENERAL INFORMATION

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	good	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations	REASON for SIGNFICANCE	
STOREFRONT INTEGRITY			
SECONDARY STRUCTURE	-		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Tudor Revival	PLAN	rectangular
DETAILS		NO OF STORIES	1.5
BEGINYEAR	c. 1930	ROOF TYPE	Side gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Concrete - block
WALL MATERIAL (current)	Brick	PORCH	
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Brick	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung
		WINDOW CONFIG	6/1

SIGNIFICANT FEATURES	See continuation sheet
ALTERATIONS	concrete front terrace; filled in arched openings on front facade; severely deteriorated front chimney

STOREFRONT FEATURES	
STOREFRONT ALTERATIONS	

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	Letter dated 9/23/1976--3-car garage demolished
LANDSCAPE	midblock on west side of four lane state highway; mixed uses on street; house built on rise; concrete retaining wall and steps and front; wrought iron stair rails; chain link fencing

PHOTO INFORMATION

ROLL1	2
FRAMES1	16
ROLL2	
FRAMES2	
ROLL3	
FRAMES3	
DIGITAL PHOTO ID	e:\main1215s.jpg

SURVEY INFORMATION

PREPARER	JENNIFER KENNY
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	3/8/2005
SURVEYAREA	Barber-Colman

City of ROCKFORD

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY
CONTINUATION SHEET

STREET # 1215

STREET S MAIN ST

ADDITIONAL PHOTOS OR INFORMATION

Significant Features

Two front gables; polychromatic brick; projecting front entry bay with asymmetrical gable; arched openings on each side of front door; chimney with stepped brick; decorative brick flower boxes under windows with corbeling; arched front entry with arched wood door and stone tabbed surround

City of ROCKFORD - Commercial/Industrial

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY

STREET #	1223
DIRECTION	S
STREET	MAIN
ABB	ST
PIN	11-27-278-012
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
CRITERIA	
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	-
Listed on existing SURVEY?	SM; RHPC

GENERAL INFORMATION

CATEGORY	building	**CURRENT FUNCTION**	Domestic - single dwelling
CONDITION	good	**HISTORIC FUNCTION**	Domestic - single dwelling
INTEGRITY	major alterations and/or addition(s)	**REASON for SIGNFICANCE**	
STOREFRONT INTEGRITY			
SECONDARY STRUCTURE	-		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Gable Front	**PLAN**	rectangular
DETAILS		**NO OF STORIES**	2.
BEGINYEAR	c. 1910	**ROOF TYPE**	Front gable
OTHER YEAR		**ROOF MATERIAL**	Ashphalt - shingle
DATESOURCE	Surveyor	**FOUNDATION**	Concrete - block
WALL MATERIAL (current)	Stucco	**PORCH**	Full Front
WALL MATERIAL 2 (current)		**WINDOW MATERIAL**	Wood
WALL MATERIAL (original)	Unknown	**WINDOW MATERIAL**	Aluminum
WALL MATERIAL 2 (original)		**WINDOW TYPE**	double hung
		WINDOW CONFIG	1/1

SIGNIFICANT FEATURES: Wood frieze in front gable; wood front door with 6 lights and a wood panel below

ALTERATIONS: Stucco cladding; rebuilt (downsized) front porch (non-historic) with hipped roof and wood rails and supports; first floor opening on front possibly enclosed or opening moved

STOREFRONT FEATURES	
STOREFRONT ALTERATIONS	

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	
LANDSCAPE	midblock on west side of four lane state highway between Loomis and Montague; mixed uses; house on rise with front sidewalk; concrete retaining wall and steps at front

PHOTO INFORMATION

ROLL1	2
FRAMES1	17
ROLL2	
FRAMES2	
ROLL3	
FRAMES3	
DIGITAL PHOTO ID	e:\main1223s.jpg

SURVEY INFORMATION

PREPARER	JENNIFER KENNY
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	3/8/2005
SURVEYAREA	Barber-Colman

City of ROCKFORD - Commercial/Industrial

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY

STREET #	1225
DIRECTION	S
STREET	MAIN
ABB	ST
PIN	11-27-278-013
LOCAL SIGNIFICANCE RATING	NC
POTENTIAL IND NR? (Y or N)	N
CRITERIA	
Contributing to a NR DISTRICT?	NC
Contributing secondary structure?	C
Listed on existing SURVEY?	SM; RHPC



GENERAL INFORMATION

CATEGORY	building	**CURRENT FUNCTION**	Domestic - single dwelling
CONDITION	fair	**HISTORIC FUNCTION**	Domestic - single dwelling
INTEGRITY	major alterations and/or addition(s)	**REASON for SIGNFICANCE**	
STOREFRONT INTEGRITY			
SECONDARY STRUCTURE	detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Gable Front	**PLAN**	rectangular
DETAILS		**NO OF STORIES**	2
BEGINYEAR	c. 1910	**ROOF TYPE**	Front gable
OTHER YEAR		**ROOF MATERIAL**	Asphalt - shingle
DATESOURCE	Surveyor	**FOUNDATION**	Concrete - block
WALL MATERIAL (current)	Stucco	**PORCH**	Full Front & Deck
WALL MATERIAL 2 (current)		**WINDOW MATERIAL**	Wood
WALL MATERIAL (original)	Unknown	**WINDOW MATERIAL**	
WALL MATERIAL 2 (original)		**WINDOW TYPE**	double hung
		WINDOW CONFIG	1/1; snap-in

SIGNIFICANT FEATURES	Dormer on south side; wood fascia and trim
ALTERATIONS	Significant alterations, including enlarged window opening to new door at 2nd floor front facade; 2 story front porch deck; replacement vinyl window in enlarged opening

STOREFRONT FEATURES	
STOREFRONT ALTERATIONS	

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	



HISTORIC INFO	#23135A (1954)--garage
LANDSCAPE	

PHOTO INFORMATION

ROLL1	2
FRAMES1	18
ROLL2	11
FRAMES2	17
ROLL3	
FRAMES3	
DIGITAL PHOTO ID	e:\main1225s.jpg

SURVEY INFORMATION

PREPARER	JENNIFER KENNY
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	3/8/2005
SURVEYAREA	Barber-Colman

City of ROCKFORD - Commercial/Industrial

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY

STREET #	1227
DIRECTION	S
STREET	MAIN
ABB	ST
PIN	11-27-278-014
LOCAL SIGNIFICANCE RATING	NC
POTENTIAL IND NR? (Y or N)	N
CRITERIA	
Contributing to a NR DISTRICT?	NC
Contributing secondary structure?	-
Listed on existing SURVEY?	



GENERAL INFORMATION

CATEGORY	building	CURRENT FUNCTION	Commerce/Trade - business
CONDITION		HISTORIC FUNCTION	Transportation - road-related (vehicular)
INTEGRITY		REASON for SIGNFICANCE	
STOREFRONT INTEGRITY			
SECONDARY STRUCTURE			

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Garage addition	PLAN	
DETAILS		NO OF STORIES	
BEGINYEAR	c. 1964	ROOF TYPE	
OTHER YEAR		ROOF MATERIAL	
DATESOURCE		FOUNDATION	
WALL MATERIAL (current)	Brick	PORCH	
WALL MATERIAL 2 (current)	Concrete - block	WINDOW MATERIAL	
WALL MATERIAL (original)	Brick	WINDOW MATERIAL	
WALL MATERIAL 2 (original)	Concrete - block	WINDOW TYPE	
		WINDOW CONFIG	

SIGNIFICANT FEATURES	Built as an addition to 1231 Main around 1964 when house at the front of the lot was demolished.
ALTERATIONS	

STOREFRONT FEATURES	
STOREFRONT ALTERATIONS	

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	
LANDSCAPE	parking lot for service station next door

PHOTO INFORMATION

ROLL1	2
FRAMES1	19
ROLL2	
FRAMES2	
ROLL3	
FRAMES3	
DIGITAL PHOTO ID	e:\main1227s.jpg

SURVEY INFORMATION

PREPARER	
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	
SURVEYAREA	Barber-Colman

City of ROCKFORD - Commercial/Industrial

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY

STREET #	1231
DIRECTION	S
STREET	MAIN
ABB	ST
PIN	11-27-278-015
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
CRITERIA	
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	-
Listed on existing SURVEY?	SM; RHPC



GENERAL INFORMATION

CATEGORY	building	**CURRENT FUNCTION**	Transportation - auto repair/gas station
CONDITION	good	**HISTORIC FUNCTION**	Transportation - auto repair/gas station
INTEGRITY	major alterations and/or addition(s)	**REASON for SIGNFICANCE**	
STOREFRONT INTEGRITY			
SECONDARY STRUCTURE			

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Gas Station/Art Moderne	**PLAN**	irregular
DETAILS		**NO OF STORIES**	2
BEGINYEAR	1942	**ROOF TYPE**	Flat
OTHER YEAR		**ROOF MATERIAL**	Not visible
DATESOURCE	Permit/So. Main Street Survey	**FOUNDATION**	Concrete - poured
WALL MATERIAL (current)	Brick	**PORCH**	
WALL MATERIAL 2 (current)	Aluminum Siding	**WINDOW MATERIAL**	Plate glass
WALL MATERIAL (original)	Brick	**WINDOW MATERIAL**	Glass block
WALL MATERIAL 2 (original)		**WINDOW TYPE**	fixed
		WINDOW CONFIG	single light

SIGNIFICANT FEATURES See continuation sheet

ALTERATIONS See continuation sheet. Addition to north, ca. 1964

STOREFRONT FEATURES	
STOREFRONT ALTERATIONS	

HISTORIC INFORMATION

HISTORIC NAME	Paris Auto Shop
COMMON NAME	Auto-Max Service
COST	
ARCHITECT	Hubbard & Hyland
ARCHITECT2	
BUILDER	Schmeling
ARCHITECT SOURCE	Building permit

HISTORIC INFO	old photo of building from 1946 in Main Street Survey; See continuation sheet for building permits
LANDSCAPE	On northwest corner of S. Main and Montague Street; west side of busy four lane state highway; asphalt parking lot at front and side; high chain link fence around side parking lot; at grade ?? To rear (west)

PHOTO INFORMATION

ROLL1	2
FRAMES1	20
ROLL2	
FRAMES2	
ROLL3	
FRAMES3	
DIGITAL PHOTO ID	e:\main1231s.jpg

SURVEY INFORMATION

PREPARER	JENNIFER KENNY
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	3/8/2005
SURVEYAREA	Barber-Colman

City of ROCKFORD

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY
CONTINUATION SHEET

STREET # 1231

STREET S MAIN ST

ADDITIONAL PHOTOS OR INFORMATION

Significant Features

2 garage bays with glass paneled wood overhead doors; curved front; unadorned yellow brick facade; shallow stone coping built in multiple volumes at top of wall; four plate glass windows set in a curve; shallow projecting canopy; original wood and glass door and transom on main portion

Alterations

1 story addition, concrete block walls [permit #9745(1943)--10x12 1-story cement block add.]; one story steel and brick addition [permit #11100(1946)-1 story brick & steel add] ; second story addition for bedrooms mow covered with Aluminum siding [permit #12674 (1948)–27x14 2nd story cement block addition for bedrooms]; large rear add. [permit #16236 (1953)–53x65 rear addition]; large addition to north side [permit #27676 (1964)–63x42 north side addition]; addition to north side [permit #29044 (1965)–11x52 north side addition]; move overhead door to Main St. side [permit #33575 (1968)–move overhead door from Montague side to Main Street, close up old opening]; enclosed garage opening in south portion on east front facade with brick & glass block; same with south facade window openings; Aluminum replacement door & transom on south portion on east front facade; replacement overhead garage door on south facade

ADDITIONAL PERMIT INFORMATION

#14236 (4/8/1942)--1 story cement block public garage; #9746B (1943)-1 story 8x10 frame add.; #25061 (1963)–general remodel and repair storefront ($1500); #27448 (1964)–cut opening and install 10x11 overhead door

1231 S. Main St.

Street & No. 1231 S. Main St. Per No. 11100 B
Owner Paris Garage
Contractor E. W. Schmeling & Sons
Architect
Class of Work 46' 7" x 92' 6" one story brick & steel add to garage for offices and service station
Lot Blk. Add. $20,000
Date Issued March 12 1946

Street & No. 1231 S Main St Per No. 97458
Owner Paris Garage
Contractor
Architect
Class of Work 10x12 one story add to garage to be used for stge- cem blk walls $ 100
Lot Blk. Add.
Date Issued July 27 1943

Street & No. 1231 S Main St Per No. 97468
Owner Sam Paris
Contractor
Architect
Class of Work 8x10 one story frame add to present stge shed $ 60
Lot Blk. Add.
Date Issued July 27 1943

Street & No. 1231 S. Main St Per No. 11236 A
Owner Samuel Paris
Contractor Charles Scandroli
Architect Hubbard & Hyland
Class of Work One story cement block public grrage 26'9 x 75'4 2500.
Lot 7 Blk. 31 Add. Church & Robertson
Date Issued April 8th, 1942 194

1231 S. Main St.

Per No. 33575 B

Location 1231 So. Main Street
Owner Paris Auto Shop
Contractor Acme Builders
Architect
Class of Work Move overhead door from Montague side to Main St. Close up old opening. $1800.
Legal
Date Issued August 12 19 68

Per No. 25061 B

Location 1231 S. Main Street
Owner O'Donnells Spr. Mkt.
Contractor Don Fox
Architect
Class of Work General remodel & repair store front. $1500
Legal
Date Issued Feb. 15 19 63

Location 1231 So. Main St. Per No. 16236B
Owner Samuel Paris
Contractor Scandroli Constr. Co
Architect Hubbard & Hyland
Class of Work 53x65 add to rear of bldg-br & blk $15,000
Lot Blk. Add.
Date Issued Oct. 9 195 3

Street & No. 1231 S Main St Per No. 12674-A
Owner Paris Garage
Contractor E W Schmeling & Sons
Architect
Class of Work 27x14 - 2nd st cem blk add for bedrooms $3000
Lot Blk. Add.
Date Issued July 27th 1948

1231 S. Main St.

Location 1231 S. Main St. Per No. 36828B
Owner Paris Auto
Contractor Mule Const
Architect
Class of Work build storage bin $250.
Legal
Date Issued Aug. 7 1970

Location 1231 South Main St. Per No. 29044 B
Owner
Contractor H & H Bldrs.
Architect
Class of Work 11x52 addn to north side of existing gar bldg. Block & frame constn. $5,000.
Legal
Date Issued Sept. 27 1965

ation 1231 South Main Street Per No. 27448 B
ner Paris Auto Shop
tractor Owner
hitect
s of Work cut opening and install 10 x 11 overhead door
al $380
Date Issued Aug 18 19 64

Location 1231 South Main Street Per No. 27676 B
Owner Paris
Contractor Nappi, Inc.
Architect
Class of Work add 63 x 42 to N side of bldg for shop & office space $8000
Legal
Date Issued Oct 6 19