

SILT FENCE

Properly installed and maintained



The silt fence is properly installed meaning it is trenched and back filled.



The silt fence is installed in the proper location.



The silt fence is installed and being maintained.

Improper installation and lack of maintenance



The silt fence is properly installed but needs maintenance. Once sediment is half way up the silt fence the sediment needs to be removed and the silt fence needs to be repaired.



Silt fence was never installed and therefore sediment is leaving the site.



Silt fence was installed improperly and never maintained. Construction debris knocked the silt fence over and sediment is leaving the site.

Mission Statement

The Stormwater Environmental Team is ultimately focused on protecting and improving the quality of local bodies of water. This is done by implementing flood control systems, water monitoring, and enforcing water-friendly construction practices that follow Environmental Protection Agency (EPA) standards. Keeping environmental issues in mind, the division strives to keep the city's water safe for recreation as well as usage at home.



Contact Us
779-348-7175



Visit Our Website
www.rockfordil.gov



Our Location
425 E. State St. Rockford, IL
61104